LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

on this certificate.

Ontonagon	Located In:	Corner Code #	
(County)	_		
1. Public Land Survey	T 52N R 37W T R	F13 (GCDB 340100)	
2. Property Controlling in Section	S 33 T 52N R 37W S T R S T R	16 (GCDB 360100)	
3. Miscellaneous Property in Sec.	S T R R		Posister of Doods Stewn 9 File Number
4. Lot No. , Red 5. Private Claims	corded Plat	· · · · · · · · · · · · · · · · · · ·	Register of Deeds Stamp & File Number A B C D E F G H I J K L I 2 - 6 - 5 - 4 - 3 - 2 - 1 -
!, Stephan J. Szyszkoski , in a field survey on 09/03/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 5			
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8			
re-established, monumented, recover	1 of Land Surveyors or by a Decree ered, found as expressed below:	of a Court of Law; established,	8 -19 -20 -21 -22 -23 -24
NOTE: Not more than 2 corn	ers all in the same town and range		10 30 29 28 27 26 25

A. Description of original monument and accessories and/or subsequent restoration:

(F13) Standard Quarter corner on the South side of Sec. 33. Previously restored and recorded in 1992 by K.L.Sackett RLS, and remonumented by the undersigned in 1999, in the 1992 position. Set 1" pipe with 4" alum. cap. 9" Sugar N63°W 36.1'; 10" Sugar N02°E 30.8'; 5" Sugar N89°E 35.8'; 24" double Oak N09°E 10.8'. Not a common 1/4 corner with Section 4, T51N-R37W.

(16-Sec. 33) East 1/16 corner on the South line of Section 33. Not previously monumented. Not a common 1/16 corner with Section 4, T51N-R37W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F13) Found the 1999 monument of record, in good condition, and at record bearing and distance from three existing 1999 witnesses.

(16-Sec. 33) Established the position for the corner on the Township Line between Standard Quarter corner 1317.05' west and Standard Section corner 1317.05' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F13) Found 1"ID I.pipe with 4" alum. MDNR cap. (16) Set 1"IDx28" I.pipe with 2" alum! MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 14" Sugar N65°W 36.45' old blazes (1992 NBT) 12" Sugar N65°E 8.6' mrkd "1/16S BT" 26" double Oak N10°E 11.0' do (1999 NBT) 5" Sugar N30°E 5.65' do 7" Sugar N89°E 36.1' dо (1992 NBT) 5" Ironwood N11°W 12.2' do 5" Oak N50°E 10.0' mrkd "1/4S NBT" 12" Oak N71°W 54.7' do Sq'd cedar post adjacent. Set sq'd cedar post adjacent. E= 7847004.449 N= 231829.360 E= 7847405.709 N= 231818.845

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 data Coord. Ref.=NGS PID RL0503: N= 233736.672 m. E= 7856830.965 m. STEPHAN J.

Surveyor's Michigan License No.

Date

09/23/2015

33986

For the Michigan Department of Natural Resources, Forest Resources Division

LAND SURVEYOR No. sed Oct.,

ZYSZKOSKI

FORM APPROVED BY MICHIGAN STATE BOARD OF