

SURVEY & REMONUMENTATION

SEP 17 1999

LIBER

2 PAGE 302

RECEIVED FOR RECORD

99 AUG -2 AM 9: 09

SECTION

1999 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 2 PAGE NO. 302
MICHELE VAN NORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

SANILAC

(County)

Located In:

Corner Code #

1. Public Land Survey

T11NR12E

A-12

T R

T R

T R

T R

2. Property Controlling in Section

S

T R

S

T R

3. Miscellaneous Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, John A. Millettics, in a field survey on April 1, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1834 (Gov't. Land Office Notes) Harvey Parke, D.S.-set quarter Section post- Cedar 11inches in diameter; Corner tree Mkd.; Cedar 9 S65W 14 Marked
1957 (Michigan State Highway Department Road Plans for Old Route M-38) "Witnesses to E1 Cor. Sec. 36" S08°E-89.18'; 6" Poplar; S85°W 21.17'; 7" Apple Tree; N57°W 26.42'; 4" poplar; witnessed to 1" pipe
1976 (Survey-Liber 467, page 60) Robert G.Kay, P.S. 14096-fnd. 1" pipe-S75°W 63.86' nail 6" Poplar; East 33.55' Monument; S30°E 153.35' Nail 6" Birch
1991 (Survey for Shannon & Scott S. Wilson) Russell L. Brown, P.S. 24588-Fnd. 3/4" Pipe S75°W 63.86' Spike in 8" Poplar; S30°E 153.35' Spike in 6" Birch; West 43.50' Spike in 6" Poplar

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A - 12

W 1/4 Corner Section 31 T11N-R12E

Found Standard Concrete Monument with Brass Cap

South 2651.04 feet to the SW Corner Section 31

North 2657.60 feet to the NW Corner Section 31

Accepted as best evidence

APPROVED PEER BOARD MEETING
July 20, 1999

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Found Standard Concrete Monument W/2" Brass Cap
S85°E, 33.58' Top 1/2" iron encased in 4" diameter Concrete Cylinder
S65°E, 106.60' T.C. Remon. tag in North face 9" White Birch
N85°W, 33.12' Fnd. 1/2" iron with cap #25859 in bottom of ditch
N82°W, 43.58' T.C. Remon. tag above found spike in North face of 6" Poplar

Signed by

Surveyor's Michigan License No. 25859

Date June 30, 1999

