## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft	Located In:	Corner Code #	F-2
(County)			**
1. Public Land Survey	T 42N R 16W	K2 (GCDB 600640)	## "
2. Property Controlling in Section	S 1 T 42N R 16W S T R	9 (GCDB 660640)	50 51
3. Miscellaneous Property in Sec.	S T R R		Register of Deeds Stamp & File Number
4. Lot No. , Re- 5. Private Claims	corded Plat		A B C D E F G H I J K I
above were in conformance with	n a field survey on (74, Michigan P.A. of 1970, the corne regulations and rules therefore as requirement of the Interior, Bureau of	uired in the current manual of surve	2 5 9 10 11 1

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

re-established, monumented, recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8

(K2) Quarter corner common to Sections 1 and 2. 1997 - Recorded by Thomas P.O'Brien PS in L4, P161 as reestablished by single proportionate measurement between K1 and K3. Set 1/2" iron bar with O'Brien cap #21274 in Monument Box. 10" Cedar N41°E 108.61', 12" Cedar S50°E 82.38', 14" Aspen West 71.20', pipe w/MDOT station cap #75070 N13°W 102.48', Carsonite Post East 50.0'. 2009 - Michael Peterson PS found the monument of record in a new monument box and verified the 1997 witnesses.

(9-Sec. 1) Center-East 1/16 corner, Section 1. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K2) Found an approx. 5/8" dia. iron bar with plastic cap #44292 in a monument box, in accord with the 1997 witnesses of record, but S89°21'37"W 39.08' (MCS83 grid brg) from the 1997 proportionate position of record. Informed Surveyor Michael Peterson PS #44292 of Schoolcraft Co. Remonumentation of the discovery of this error and reestablished the position for the corner on the Section line between Section corner K3 2679.63' (40.00 ch. US) south and Section corner K1 2710.45' (40.46 ch. US) north, being proportionate to the U.S. record.

(9-Sec. 1) Established the position for the corner midway and on a straight line between Quarter corner 1329.53' east and the intersection of 1/4 lines of Section 1, 1329.53' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

13" Cedar S26°E 53.90' mrkd "1/4S" do 6" 1 10" Cedar S4°5E 52.18' do 7" 1 15" Aspen N88°W 110.43' (to exist. nail) do 7" 1 17 Cep center R/W marker N31°E 79.33' 12" 12" 12"	Set 1"IDx28" I.pipe with 2" a measuring nail with MDNR tag R.Pine S31°W 7.37' mrkd R.Pipe S82°W 17.79' R.Pine N26°W 23.85' R.Pine N48°E 33.67' 8058336.465 N= 142541.573	in the side of:
--	--	-----------------

Bearings are magnetic.	Coordinates	are MCS83 in	n meters	(NAD83 (2011)	Datum
Coord. Ref.=NGS PID	DL6164: N=	131822.939	m. E= 80	59239.498 m.	1

Signed by

Date

Surveyor's Michigan License No.

02/04/2015

10

11

For the Michigan Department of Natural Resources, Forest Resources Division

SURVEYOR FORM APPROVED BY MICHIGAN STATE BOARD

AND SON Revised Oct., 1995

STEPHAN J

SZYSZKOSKI

LAND