LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:		Corner Code #	,		
1. Public Land Survey	T 42N	R	K3 (GCDB 600600)			
2. Property Controlling in Section	S 1 T 42N S T S	R 16W R R	14 (GCDB 700620)	55		
3. Miscellaneous Property in Sec.	S T S	R		Parking of D. A.		
4. Lot No. , Red 5. Private Claims	corded Plat			A B C D E	S Stamp & File Number	r K L I
I, Stephan J. Szyszkoski, in that under requirements of P.A. above were in conformance with a instructions of the United States II a Court of Law and /or that the cute rules of the Michigan Board re-established, monumented, recovery	74, Michigan P.A. of 197 regulations and rules ther Department of the Interiororner points mentioned in d of Land Surveyors or	0, the corner efore as requir r, Bureau of La lines 3, 4 and by a Decree	ed in the current manual of surve and Management or by a decree of 1.5 above were in conformance with	3 4 7 8 9 9 9 10 16 17	-9 - 10 - 11 - 16 - 15 - 14 - 22 - 23 -	13
NOTE: Not more than 2 corn	ers, all in the same to	wn and range	, may be recorded	10 30 29	-262726	25—
on this certificate.				11 12 31 32	.33 34 35	-36
A. Description of original m	onument and accesso	ries and/or	subsequent restoration:			

- (K3) Section corner common to 1-2-11-12. 1997 Remonumented by Thomas P. O'Brien PS 21274 with a Schoolcraft County monument. 13" Cedar S10°E 23.48', 13" Cedar S09°W 22.17', 10" Cedar S18°W 12.93', 7" twin Cedar S16°E 22.40', 8" Cedar N65°W 138.30', 6" Tamarack N66°E 96.79', Carsonite Post North 1.0'. Corner approved by Schoolcraft County Peer Group 11/12/97 and recorded in L 4, P 140.
- (14-Sec. 1) South 1/16 corner between Section 1 T42N-R16W and Section 6 T42N-R15W. 1967 Established by Frank J. Bray, RLS midway and on line between section corner to south and 1/4 corner to north. Set 1" iron pipe with 4" aluminum cap. 17" R.Pine S37°E 14 links, 17" R.Pine N34°W 39
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K3) The 1997 monument was not recovered. At the position reestablished at record bearing and distance from the 1997 witnesses, I found a hole in the mucky soil which I accepted as the remaining physical evidence of the position of the 1997 monument. This position checks with the 1997 witnesses of record, all of which are in good condition and remeasured as shown below. Set 1"ID iron pipe with 4" Michigan Dept. of Conservation cap at said position, flush with the ground surface.
- (14-Sec. 1) Found the 1967 monument in good condition, substantially at the record position, and at record bearing and distance from the 1967 witnesses, now both rotted stumps. Accepted the monument as a careful and faithful establishment of the position of the corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K3) Set 1"ID x36" I.pipe with 4" Michigan Dept. of		
Conservation tablet, flush. Found measuring nails in the following witnesses of record: 4" Cedar S14°W 12.90' 6" Cedar S10°W 22.11' 4" twin Cedar S04°E 23.52' 1" twin Cedar S18°E 22.50' 1" Cedar N62°W 137.87' " Tamarack N66°E 96.8' = 8057137.433 N= 141702.158	(14) Found 1"ID Iron pipe with 4" of Conservation cap. Set measurint tag in the side of: 10" W.Pine N27°E 6.96' mrkd 7" R.Pine S71°E 5.64' 7" R.Pine S31°W 20.66' 6" R.Pine N54°W 32.85' E= 8058751.178 N= 142145.245	alum. MI Dept. g nail with MDNI "S1/16 BT" do do do
		a material state of

Bearings are magnetic. | Coordinates are MCS83 in meters (NAD83(2011) Datum Coord. Ref.=NGS PID DL6164: N= 131822.939 m. E= 8059239.498 m.

Signed by

Date

02/10/2015

Surveyor's Michigan License No.

33986 For the Michigan Department of Natural Resources, Forest Resources Division

SURVEYOR No. 33986 FORM APPROVED BY MICHIGAN STATE BOARD OF ANDRE

STEPHAN J SZYSZKOSKI

LAND

Revised Oct., 1995