LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft	I manta d Inc					
(County)	_ Located In:	Corner Co	de#			
Public Land Survey Property Controlling	T 43N R T R T R T R S 15 T 43N R				TF 79	
in Section	S 15 T 43N R	15W 13			(5)	
3. Miscellaneous Property in Sec. 4. Lot No. Rec.	S T R S T R S T R			Register of Deec	ds Stamp & File Number	r
5. Private Claims	corded Plat	7.5		ABCDE	FGHIJ	V 7 14
that under requirements of P.A. above were in conformance with instructions of the United States I a Court of Law and /or that the other rules of the Michigan Board re-established, monumented, recovery	74, Michigan P.A. of 1970, the regulations and rules therefore Department of the Interior, Burcorner points mentioned in lines d of Land Surveyors or by a	as required in the current reau of Land Management 3, 4 and 5 above were in a Decree of a Court of	c manual of survey or by a decree of conformance with 7 Law; established, g	6 -18 -17 7 - 8 -19 - 20 - 9 9 - 10 - 30 - 29 - 11	3 2 3 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	-12132425
A Description of the				3 31 32	-33 34 35	36-

A. Description of original monument and accessories and/or subsequent restoration:

(13-Sec. 15) Southeast 1/16 corner, Sec. 15. 2003 - Position monumented by M.Peterson PS at the intersection of 1/16 lines. Set 5/8"x18" capped rebar.

(H7) Quarter corner common to Sections 15 and 22. 1965 - Original corner position perpetuated by F.J.Bray RLS from 2 original BTs, W.Pine 28" S35°E 26 links and W.Pine 26" N80°W 29 links. Set 1"Iron pipe with 4" alum. cap. 13" W.Pine N79°E 46.5 links, 6" W.Pine N17°W 40 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(13-Sec. 15) Found the 2003 monument in good condition and substantially at the record position. Accepted same as a careful and faithful establishment of the position of the corner.

(H7) Found the 1965 monument in good condition, at record bearing and distance from the 1965 NBT W.Pine NE, in good condition; the W.Pine NW, now a stump; and the stump remains of the original BT w.Pine S25°E 26 links. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(13) Found 5/8" rebar with plastic cap #44292 Set measuring nail with MDNR tag in the side of: 5" Maple S31°E 17.75' mrkd "SE1/16 BT"	(H7) Found 1"ID I.pipe with 4" alum. MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
12" Maple S40°W 4.55' do 7" Maple N47°W 20.15' do 7" Maple N37°E 2.55' do E= 8064743.103 N= 148690.074	16" Cedar N69°W 35.25' mrkd "1/4S NBT" 14" W.Pine N46°W 6.5' do 6" W.Pine S44°E 11.35' do 20" W.Pine N84°E 31.7' mrkd "1/4S" 1965 NBT E= 8064346.012 N= 148287.977

	Bearings		_		ates are	MCS83	in	meters	(NAD83 (2011)	Datum)	
	Coord.	Ref.:	=NGS PID	DL6164:	N= 1318	122.939	m. I	E= 8059	239.498 m.	dis	C OF MIC
	100	1	1 /	0	/			_	233.130 m.	AT A	
signed by	Stath	• .	Va.	12 KM	(Date		07/05/00 40	A	STEPHAN J.
	anger 2	 /	4 74	gus			Jale	_	07/25/2013	901	STEFFIAN J.
Surveyor's Michi	gan Ličense No	o. /	, , ,	33	3986					11	SETSENCISK

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROPESSION

d 4, 1983 Oct., 1995

LAND