

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 44N R 15W	F7
	T 44N R 15W	G7
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on F7 08/05/2009 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F7) Quarter corner common to Sections 16 and 21. 1965 - Corner recovered by F.J.Bray RLS and  
recorded in 1965 as follows: "This corner was set by unknown surveyor from stump of original BT  
Y.Pine 12" N15W 25 links. Lower blaze with scribe marks "BT" is present on stump. Found 3/4" pipe  
encased in a 4" concrete cylinder cast in a 4" stove pipe the whole of unknown length". 6" Jack Pine  
N07E 32.5 links, 7" Jack Pine S53W 81 links.

(G7) Corner common to Sections 15-16-21-22. 1975 - Remonumented by David B. Babbitt, RLS in the  
original position at record bearing and distance from original BT stump found with "very plain lower  
face and hack mark". Set 1"ID I.pipe with 4" aluminum MDNR cap. 12" W.Pine S18W 26.4', 6" W.Pine  
S75E 11.5'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F7) Found the monument described in the 1965 record in good condition (stove pipe no longer visible)  
and at record bearing and distance from the two 1965 witnesses. The Jack Pine NE is in good  
condition. The Jack Pine SW is a stump with bottom blaze visible. The original BT Y.Pine NW is a  
stump with no markings visible, at record bearing and distance.

(G7) Found the 1975 monument in good condition and at record bearing and distance from the 1975  
witnesses, both in good condition. Accepted same as a careful and faithful perpetuation of the  
position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F7) Found 3/4" I.pipe in 4" concrete cylinder.  
Set measuring nail with MDNR tag in the side of:  
12" J.Pine N09E 21.8' mrkd "1/4S" 1965 NBT  
7" J.Pine N63W 50.7' mrkd "1/4S NBT"  
11" J.Pine N33W 10.0' do  
6" J.Pine S88E 21.22' do  
Bearings are magnetic.

(G7) Found 1"ID I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
18" W.Pine S20W 27.04' mrkd "S21" 1975 NBT  
9" W.Pine S72E 11.54' mrkd "S22" do  
6" W.Pine N07W 13.86' mrkd "S16 NBT"  
6" Spruce S74W 2.59' "S21 NBT"  
Bearings are magnetic.

Signed by

Stephan J. Szyszkoski

Date

01/26/2010

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

