

54

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Schoolcraft  
(County)

Located In:

Corner Code //

1. Public Land Survey	T 46N	R 13W	C10
	T	R	
	T	R	
	T	R	
2. Property Controlling	S 29	T 46N	R 13W
in Section	S	T	R
3. Miscellaneous	S	T	R
Property in Sec.	S	T	R

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Stephan J. Szyszkoski, in a field survey on September 20, 1994, 19\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

**A. Description of original monument and accessories and/or subsequent restoration:**

(C10) Quarter corner common to Sections 29-30. Corner reestablished and recorded in 1961 by Billy D. Buckler RLS, as follows: "This corner was reestablished midway and on line between two section corners. No evidence of original corner. Corner monument 1" pipe with 4" brass cap. Witnesses to corner 5" Jack Pine N80E 25 links, 5" Jack Pine N08E 23.5 links". Found no subsequent record.  
(2-Sec. 29) East 1/16 corner between Sections 20-29. Michigan Department of Natural Resources field notes dated 1964 indicate that a wood post was placed at the corner following a survey along the North line of Section 29. Found no subsequent record.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(C10) Found and accepted Buckler's monument, a 1" I.D. iron pipe with a 4" brass Michigan Dept. of Conservation cap, at record bearing and distance from his 1961 NBTs. Both trees are in good condition and are now 10" diameter. Left the monument in place and marked two new witnesses as described below.  
(2-Sec. 29) Recovered a 1" pipe with 4" Michigan Department of Natural Resources cap near the corner position. No record was found indicating who placed this corner, and the cap is unstamped. The found pipe falls 2.6' west and 6.3' south of the corner position subsequently monumented. A 4" squared wood post was found adjacent to the pipe. I did not accept the pipe as marking the corner. Established the corner on a straight line between 1/4 corner 1321.48' west and Section corner 1321.48' east. At the position for the corner, I placed a 1" I.D.x36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(C10) found 1" iron pipe with 4" brass cap. Blazed, scribed and set measuring nails with tags in the following new bearing trees:  
8" Jack Pine S61E 3.3' 1/4S NBT"  
4" Spruce S66W 19.9' 1/4S NBT"  
Bearings are magnetic.

(2) Set 1" pipe with 4" MDNR cap. Blazed, scribed, and placed measuring nails in the following bearing trees:  
6" Spruce N76E 15.1' "E1/16 BT"  
6" Spruce S32E 14.9' "E1/16 BT"  
6" Spruce S25W 12.95' "E1/16 BT"  
4" Spruce S45W 14.6' "E1/16 BT"  
Placed 4" squared and scribed cedar post and 4" squared tamarack post adjacent. Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 12-7-1994  
Surveyor's Michigan License No. 33986