## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

				X2 33	
Schoolcraft	Located In:	Corner Code #	242		
(County)					
1. Public Land Survey	T 46N R 13W	/ E12			
2. Property Controlling in Section	S T R S T R			8	
3. Miscellaneous Property in Sec.	S T R		Register of Deep	ds Stamp & File Numb	her
4. Lot No. Rec 5. Private Claims	corded Plat		A B C D E	F G R I J	K L M
above were in conformance with instructions of the United States	74, Michigan P.A. of 1970, the corregulations and rules therefore as re Department of the Interior, Bureau	do hereby state ner points mentioned in lines 1 and equired in the current manual of surv of Land Management or by a decree	yey 5 of 6 18 17	-161514	12-13-
	d of Land Surveyors or by a Dec	cree of a Court of Law; established	1 - 1 - 1 - 1	23 22 33	24
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town and ra	nge, may be recorded	10 30 29 11 12 31 32	-26 27 -26 -33 -34 -35	36

A. Description of original monument and accessories and/or subsequent restoration:

(E12) Quarter corner common to Sections 32 and 33. 1850 - Established by Guy Carleton, U.S. Deputy Surveyor, midway and on the line between Section corners 39.69 chains north and south. Cedar 10" N70W 4 links, Cedar 8" S51E 4 links. 1979 - Corner monumented by Billy D. post. Buckler RLS. Set 1" pipe with 4" alum. cap. 8" Cedar N54E 5.1', 7" Cedar N42W 11.0'. drawing dated June 18 1979, Mr. Buckler notes the distance north to E11 as 2620.2' and the angle between the Section line and the E-W 1/4 line (in NE quadrant) of 89 deg. 52'. 1991 - Thomas P. O'Brien PS records 1/16 cor. #8, east of E12, noting that its position was established by "section subdivision". According to an undated partial sketch of Section 33 by Mr. O'Brien, the mile E11 to E13 measures 5196.72', E13 having been remonumented by himself in accord with "found maples which match GLO corner tree and witness tree pattern". Mr. O'Brien does not indicate E12 on the sketch in any manner whatsoever but describes 1/16 cor. #3 (noted as "no corner set") as being 1299.18' south of Ell. 2002 - Robert Goodreau PS notes on a survey drawing for Seney Township that the corner is recorded in L1, P.219 Schoolcraft Co. Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E12) Found the 1979 monument in good condition and at record bearing and distance from the remaining 1979 witness Cedar N42W 11.0', now 12" DBH with old open blaze. The method which Mr. Buckler used to determine the corner position is not known. No explanation or formal Land Corner Certificate was Distance north to E11 was found to be 2619.04' and the angle between the Section line and the E-W 1/4 line (to the E1/4 cor. of Sec. 33) was found to be 89 deg. 50'58". The notation by Mr. Goodreau appears to be in error, as no record of this corner is to be found in L.1, P.219 of Land Corner Records. The position of Mr. O'Brien's monuments (1/16 #8 and Center F12) suggest that either these corners were set in erroneous positions or that their positions were not controlled by the 1979 I accept the DNR monument as the best available evidence of the position of the monument at E12. original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E12) Fd. 1"ID Iron pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 12" Cedar S05W 0.8' fd. blazed on 4 sides 12" Cedar N41W 11.4' open blaze (1979 NBT) 7" Cedar S63W 4.2' mrkd "1/4S NBT" 5" Cedar S66E 27.8' Bearings are magnetic.

SZKOSK AND

Signed by

Surveyor's Michigan L

Date

02/28/2012

For the Michigan Department of Natural Resources, Forest Resources Division