

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft

(County)

Located In:

Corner Code #

1. Public Land Survey

T 46N R 14W

E4

T 46N R 14W

E3

T R

S

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

Oct 06 2006

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 20\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E4) Quarter corner common to Sections 8 and 9. 1962 - Reestablished by single proportionate measurement between Section corners by Billy D. Buckler RLS. Set 1" pipe with 4" brass cap. Witnesses: 17" W.Pine S35W 70 links, 14" Hemlock S50E 24 links.  
(E3) Corner common to Sections 4-5-8-9. 1962 - Reestablished by Billy D. Buckler RLS "on line between 1/4 corner 1/2 mile north and a line tree 1.5 miles south. Distance east to 1/4 corner is good". Set 1" pipe with 4" brass cap. Witnesses: 9" Hemlock S8W 13.5 links, 9" Hemlock S27E 13 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E4) Recovered the 1962 monument in good condition, projecting about 1 foot, leaning slightly to the SW. My measurements show the top of the monument is 1.3' east of the record proportionate position. The 1962 witnesses were found at record bearing and distance. The W.Pine is now a stump, the Hemlock is in good condition. I accept the monument as a careful and faithful reestablishment of the position of the original corner.  
(E3) Recovered the 1962 monument in good condition and at record bearing and distance from the 1962 witnesses, both in good condition. Measured the distance to F3 and found it to be 2647.00' (GLO record = 40.1 chains). Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E4) Found 1" ID I.pipe with 4" brass MI  
Dept. of Conservation cap. Set  
measuring nails in:  
18" Hemlock S50E 16.6' mrkd "1/4S" \*  
11" Hemlock N55E 28.78' "1/4S NBT"  
11" Maple N72W 13.49' do  
10" Maple S29E 9.86' do  
Bearings are magnetic. Distances are to  
nail with tag. \* denotes 1962 NBT.

(E3) Found 1" ID I.pipe with 4" brass MI  
Dept. of Conservation cap. Set  
measuring nails in:  
14" Hemlock S13W 9.06' mrkd "S8" \*  
15" Hemlock S24E 8.4' "S9" \*  
5" Hemlock N45E 8.59' mrkd "S4 NBT"  
7" Cherry N85W 24.85' "S5 NBT"  
Bearings are magnetic. Distances are to  
nail with tag. \* denotes 1962 NBT.



Signed by

*Stephan J. Szyszkoski*

Date

12/28/06

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995