

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 16W	F5
	T 46N R 16W	E3
	T	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 06/11/13 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F5) Quarter corner common to Sections 9 and 16. 1952 - Dean C. DeLaMater RLS remonumented the  
corner from one original B.T. still in place, good condition. The original BTs were: Beech 8" N71°E  
3 links, Beech 10" S39°W 29 links. Set 1"ID I.pipe with 4" brass cap. NBTs: 6" S.Maple N8°E 8  
links, 10" S.Maple S74°E 57 links.

(E3) Corner common to Sections 4-5-8-9. 1952 - Dean C. DeLaMater RLS remonumented the corner from  
one original B.T. still in place, down, fair condition. The original BTs were: Cedar 15" S44°E 20  
links, Cedar 10" N42°W 15 links. Set 1"ID I.pipe with 4" brass cap. NBTs: 6" Cedar N40°W 41 links,  
9" Cedar N70°E 27 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F5) Found the 1952 monument in good condition and at record bearing and distance from the rotted  
stump remains of the 1952 accessories. The original BT Beech S39°W 29 links is a rotted stump with  
blaze and scar, at record bearing and distance. Accepted the monument as a careful and faithful  
perpetuation of the position of the original corner.

(E3) Found the 1952 monument in good condition and at record bearing and distance from the 1952  
accessories. The Cedar NW is in good condition. The Cedar NE is a stump. The original Cedar BT  
S44°E 20 links is a stump mound at record bearing and distance. Accepted the monument as a careful  
and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F5) Found 1"ID I.pipe with 4" brass MI Dept. of  
Conservation cap. Set measuring nail with MDNR tag  
in the side of:

14" Hemlock S36°E 53.75' mrkd "1/4S NBT"  
10" Maple N29°E 10.65' do  
10" Sugar N46°W 28.8' do  
14" Sugar S05°E 30.05' do  
E= 8052766.474 N= 178784.532

(E3) Found 1"ID I.pipe with 4" brass MI Dept. of  
Conservation cap. Set measuring nail with MDNR  
tag in the side of:

9" W.Birch S76°E 12.7' mrkd "S9 NBT"  
5" Cedar N86°W 13.5' "S5 NBT"  
7" Cedar N27°W 21.85' "S5 NBT"  
12" Cedar N66°E 21.45' "S4 NBT"  
E= 8051946.096 N= 180395.453

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Dat  
Coord. Ref.=NGS PID RK0046: N= 173923.068 m. E= 8052746.340 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 10/10/2013

For the Michigan Department of Natural Resources, Forest Resources Division

