LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Schoolcraft	Located in:	Corner Code #	
(County)			
1. Public Land Survey	T <u>47N</u> R T R		
Property Controlling In Section Miscellaneous Property in Sec.	TF S TF S TF		

Register of Deeds Stamp & File Number

4. Lot No	, Recorded Pl	.at	
E Drivata Claime			

May 21 1996

L Stephan J. Szyszkoski in a field survey on 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Burseu of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformence with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

		•		_					<u> </u>	<u> </u>		
1		Γ.										
2	<u>(</u>	6—	-	5—	-	<u> </u>	- -:	1		?⊢	1	1
3		L			L.,						_	
-							ا			. 1	l J	LΙ
4	<u> </u>	?		8—	— i	9-	ı	٩		1		1
5	_	╙	_	-		_	-	Н	_	_	-	-
	١.	Ļ	IJ	ן,	ן, ו	6—	ا. ا	.	_,		ַ, ַ	<u>, </u>
6	<u>—</u> ,	. 0 —	_;		,	•	_ <u>'</u>	5	_,		٦	ĭ
7	⊢	•	\vdash	-	 	-		\vdash			-	\dashv
8	L1	ا وا	2	<u>_</u>	L2		2	2	2	3	2	4—
	ľ	1		ĺ		ĺ						
٩	₽—		_	_	\vdash		_					
10	<u> 3</u>	<u></u> ە	2	و	 2	8-	-2	7_	-2	6	-2	5
		l			ĺ	l						
11	$\overline{}$	Г										
12	—ა	11	⊢ 3	2	 ⊸³	3	 —³	4-	ر—ا	5	<u>—</u> 3	6
٠.			L	l			l			L	L	Ш

A. Description of original monument and accessories and/or subsequent restoration: (A9) Corner common to Sections 19-30 T47MRI3M and 24-25 T47MRI4M. Corner remonumented in 1956 by Billy D. Buckler, RLS, from two original BTs. Corner monumented with a 1" pipe with 4" brass cap and the following: 20" M. Pine S87W 170 links, 18" A. Pine M36W 168

links. (87) Quarter corner common to Sections 18-19. Corner reestablished in 1959 by Billy D. Buckler, RLS, by proportionate measurement.

Corner monumented with a 1° pipe with 4° brass cap and the following: 18° M. Pine stump N40M S9 links, 36° M. Pine stump S08E 94 links, 16" W. Pine stump N72E 49 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

(A9) Found the 1956 monument, as described, in good condition, and at record bearing and distance from the 1956 witnesses, now both found as cut stumps. The 18° N36N has measuring notch showing. Left the monument in place and marked 4 new accessories as described below. Corner remitnessed by T.Stark and D.Lampela, Memberry.

(B7) Found the 1959 monument as described, in good condition, and at record bearing and distance from the remaining 1959 witness 18° M. Pine stump M40W 59 links. The other two witness stumps have been destroyed. Left the monument in place and marked 4 new accessories as described below. Corner rewitnessed by T.Stark and D.Lampela, Memberry.

C. Description of monument for corner and accessories established to perpetuate locating the position of the comp (B7) Found 1" pipe with 4" cap. (A9) found 1" pipe with 4" brass cap.

Blazed, scribed, and set measuring nails Blazed, scribed, and set measuring mails in the following: in the following: 5" W. Pine S66E 26.45" "S30 M8T" 12" W. Pine S29E 49.00" 30' W. Pine S69W 135.1' "S25 MBT" 11" W. Pine S88W 23.45" "\$24 NBT" 9" N. Pine N34N 39,40" 10° R. Pina N11W 29.05' 8" R. Pine S34E 23.65' "S30 MBT" 6" N. Pine N69E 58.90'

Placed a squared and scribed cedar post Placed location tag on blazed 12" W. Pine N83W approx. 133' from corner. adjacent. Bearings are magnetic. Bearings are magnetic.

of Mich STEPHAN J SZYSZKOSKI LAND SURVEYOR (Ano t

53986 Surveyors Michigan License No

"1/45 NBT"

"1/45 HBT"

"1/45 MBT"

"1/45 MBT"

For the Michigan Department of Natural Resources - Forest Management Division