NOV 1\_0 1997

COMMISSION

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

97 OCT 15 PH12: 15

REGISTER	0F	DEEDS
KERMIN	٠٠٠,	,

For corners in						REGI	STER	); UCE	เบจ
ShiaWassee (County)	Located In: Corner Code #  Middlebury Township			SHIAWASSEE COUNTY, MICH					
1. Public Land Survey	T 7N R 1E T R T R	M-10							
Property Controlling S in Section S     Miscellaneous S Property in Sec. S	T R T R T R T R T R T R		Registe	er of D	eeds S	Stamp	& File	Numb	er
4. Lot No, Record 5. Private Claims	ed Plat			A B	C D	E F	е н	IJK	L M
			2	6	5	4	3	2	1
I, Wendy A. Papineau	, in a field	survey on <u>June</u> 1 P.A. of 1970, the corner points mention	1997 4	7	8	9	10	11	12
in lines 1 and 2 above were in conf current manual of survey instructions	formance with regulations of the United States Dep	and rules therefore as required in partment of the Interior, Bureau of La orner points mentioned in lines 3, 4 an	the and 6	18	17	16	15	14	13
above were in conformance with the	rules of the Michigan Boa	ard of Land Surveyors or by a Decree of re-monumented, recovered, found	of a .	19	20	21	22	23	24
NOTE: Not more than 4 corne	rs, all in the same tow	n and range, may be recorded	10 11	30	29	28	27	26	25
on this certificate.  A. Description of original mo	nument and accessori	es and/or subsequent restoration	12	31	32	33	34	35	36

### M-10 Standard 1/4 Corner Section 25, T7N-R1E

Wood post placed by R. Thomas, D.S., Jan. 1831 S 79 W 5 lks (3.30') 9" Elm N 12 E 18 lks (11.88') 20" Sugar

L.C.R.C. by J.S.Fokens, 1976, recorded L.2, P.62 S.C.R. Set PK nail, on a straight line between NE corner Section 25, T7N-R1E & the NW corner of Section 30, T7N-R2E. Set on physical centerline

of Hammond Rd. \$ 50 W 37.32' S. end 24" CMP \$ 40 W 45.08' Road Sign N 45 W 36.06' N. end 24" CMP

Survey by O.H.Johnsrud, 1976, recorded L.2, P. 433, S.C.R. See L.C.R.C. L.2 P. 62, S.C.R.

# County Remonumentation 10 oct 97

L.C.R.C. by M.L. Vanraemdonck, 1987, recorded L.2 P.465 S.C.R. re-established corner using ties from previous recording, monument was a PK nail-not found. Set a railroad spike S 50 W 37.32' S. end 24" C.M.P. N 45 W 36.06' N. end 24" C.M.P. N 30 E 52.56' T/C S. end 12" Concrete Culvert N 20 E 88.17' PK S. Fc R.R. tie post-at top

Surveys by M.L. Vanraemdonck, 1986 & 1996, recorded L.4, P. 574 and L.7 P.669 S.C.R. See L.C.R.C. L.2 P.466 S.C.R.

L.C.R.C. by M.L. Vanraemdonck, 1996, recorded L.2 P.986 S.C.R. replaced R.R. spike  $w/\ 1/2"\ x\ 18"$ long rod w/cap #24622. Installed monument box East 22.00' S. edge S. leg arrow stop sign S 55 W 42.68' Road name sign post N 20 E 89.17' PK S. Fc R.R.tie post N 45 W 36.06' Top cent N. end 24" CMP

Pecr Review Group
Description of corner evidence found and/or method applied in restoring or reestablishing corner:

## M-10 Standard 1/4 Corner Section 25, T7N-R1E

Fnd 1/2" rod w/cap #24622 in Monument box per above records. This position fits well with a split between the Northeast & Southeast corners, Section 25, T7N-R1E (South = 2631.38' North = 2633.89') and 0.06' W of a straight line between said two corners.

There appears to be no conflicting evidence and is accepted as the best available evidence of the position of the original corner.

Approved by the Shiawassee County Peer Review Group, Sept. 4, 1997.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

## M-10

Standard 1/4 Corner Section 25, T7N-R1E
Replaced 1/2" rod with cap #24622 with a standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument between the standard 20" Harrison monument in existing monument in existing

22.01' South edge of southerly leg of double arrow sign

S55W 42.671

Road name sign post PK nail in South face railroad tie post 88,17 N20E

41919

36.061 Top center North end 24" C.M.P. \$50W 37.33'

Top center North end 24" C.M.P.

Top center south end 24" C.M.P.

PK nail and tag #12018 in centerline Baldwin Rd. (A-10 T7N-R2E)

fapineau

E 05 10 10 11 10

WENDY

A. PAPINEAU

**PROFESSIONAL** 

SURVEYOR No. 41919

POFESSIO

Surveyor's Michigan License No.