

SURVEY & RECONSTITUTION

FEB 18 1994

COMMISSION


Gladwin County Remonumentation

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

06 29 '93 AM

For corners in

Form with fields for Gladwin (County), Located In, Corner Code #, and numbered sections 1-5 for survey details.



GLADWIN COUNTY REGISTER OF DEEDS
Donnie Down

Register of Deeds Stamp & File Number

I, Craig W. McVean, in a field survey on October 26, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules...

Grid table with columns A-M and rows 2-13, containing numbers 1-36.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-12 Found post set - J. Brink, 1837. Pine 40" S 20° W 5 Lks. Hemlock 9" N 46° W 24 Lks.

M-13 Set post - H. Parke, 1831. Maple 15" S 42° E 20 Lks. Pine 9" N 82° W 17 Lks.

GLO Resurvey - 1877, T. Merrill. L.C.R.C. - P. 326-1989 - Case - iron in mon. box. M.D.O.T. right-of-way map - file #26-A-2- Con. Sec. 26031, Sheet #29 - shows - 1/4 corner for Section 4 (E-2 - T17N - R1E) but this is position for 1/4 corner to Sec. 36 (M-12 - T18N - R1W), also shown on 1959 M.D.O.T. construction plans as E-2.

GLO Resurvey - 1877, T. Merrill. M.D.O.T. witness card - 1961 - Gilbert - 3/4" rod in mon. box. L.C.R.C. - P. 77-1974 - Lapham - iron in mon. box. Record Survey L. 1, P. 350-1974. M.D.O.T. right-of-way map - file #26-R-2, control Section 26031, Sheet 29. Dundas witnesses - prior to 1958.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-12 Found 1/2" rebar in mon. box per L.C.R.C. - P. 326. M.D.O.T. distances N & S agree as shown on right-of-way map. Monument accepted as the best available evidence of position of the original corner. Accepted by Gladwin County Peer Review Group on 12-10-93.

M-13 Standard Township corner for T17&18N, R1W. Found 3/4" iron rod in mon. box per L.C.R.C., M.D.O.T. witness card and recorded survey. Monument accepted as the best available evidence of the position of the original corner. Accepted by Gladwin County Peer Review Group on 12-10-93.



C. Description of monument for corner and accessories established to perpetuate localing the position of the corner:

M-12 Replace 1/2" x 18" rebar with 2" Gladwin County alum. cap on 5/8" x 36" rebar in mon. box 0.9'± E of the centerline of M-30. S 20° E 129.90' to nail and tag in E side P.P. S 60° W 147.39' to NE corner House #2742 Foundation. S 50° W 166.76' to SE corner House #2742 Foundation. N 40° E 59.63' to nail and tag in NW side P.P. N 80° E 45.73' to nail and tag in S side 14" Maple.

M-13 Replace 3/4" x 36" Iron rod with 2" Gladwin County alum. cap on 5/8" x 36" rebar in mon. box - 1.5'± E of the centerline of M-30. N 45° E 61.80' to nail and tag in NW side 10" Maple. N 65° W 129.27' to nail and tag in S side Twin 12" Oak. S 55° W 95.96' to nail and tag in N side 12" Maple. S 50° E 119.22' to nail and tag in N side 8" Elm.

Signed by Craig W. McVean Date 12/20/93
Surveyor's Michigan License No. 39088