

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

*Marquette*

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>43</u> N. <u>24</u> E. <u>X.</u> S. R. W.	<u>K-1, K-2</u>
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. _____ E. _____ S. R. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. _____ E. _____ S. R. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Frank J. Bray do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on June 24 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- K-1 Woodpost:**  
 Hemlock 15 N55°E 5 links  
 Hemlock 10 N80W 37 links  
 W. Pine 20 S42°E 7 links  
 Hemlock 15 S31°W 47 links
- K-2 Woodpost:**  
 Cedar 7 S56°E 8 links  
 Cedar 12 S57°W 10 links

Subsequent monument: Woodpost

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- K-1** This corner was replaced from W. Pine original B.T. to SE. B.T. has been burned but both faces and notch visible. Rotted Hemlock stumps to SW and NE in proper position for other B.T.'s. Hemlock to NW is gone.
- K-2** This corner was replaced from woodpost set by Forester Metsa 20 years ago with both B.T.'s present. Both now in poor condition but some scribe marks still visible.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**ALL:** 1" iron pipe with 3/4" aluminum cap. All bearings are magnetic.

- |            |                                      |
|------------|--------------------------------------|
| <b>K-1</b> | 8" W. Spruce (S36) (NBT) N02°E 31.8' |
|            | 8" R. Maple (S2) (NBT) S33°W 32.2'   |
| <b>K-2</b> | 7" Cedar (4S) (NBT) N79°E 15.3'      |
|            | 1 1/2" Cedar (4S) (NBT) S17°E 9.5'   |

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY DATE \_\_\_\_\_

APPROVED AND SIGNED BY Frank J. Bray DATE 7-8-74  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)  
**(Frank J. Bray)**

SURVEYOR'S MICHIGAN REGISTRATION NO. 13575