## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger (County)	_ Located In:	Corner Code #			
1. Public Land Survey	T 47N R 17W	M9 (GCDB 700300)			
2. Property Controlling in Section	S T R S T R	M7 (GCDB 700400)			
3. Miscellaneous Property in Sec.	S T R				
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number  1 B C D E F G H I J K L M		
above were in conformance with instructions of the United States a Court of Law and /or that the	74, Michigan P.A. of 1970, the corner regulations and rules therefore as requi Department of the Interior, Bureau of I corner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree	ired in the current manual of survey Land Management or by a decree of d 5 above were in conformance with	3 4 - 7 - 8 - 9 - 10 - 11 - 12 - 15 - 14 - 13 - 17 - 16 - 15 - 14 - 13 - 17 - 18 - 17 - 18 - 17 - 18 - 18 - 18		
NOTE: Not more than 2 corr on this certificate.	ners, all in the same town and rang		10 30 29 28 27 26 25 11 12 31 32 33 34 35 36		
A. Description of original monument and accessories and/or subsequent restoration:  (M9) Section corner common to Sections 19-30 T47N-R16W and Sections 24-25 T47N-R17W. 1958 -					

(M7) Section corner common to Sections 18-19 T47N-R16W and Sections 13-24 T47N-R17W. 1958 - Reestablished by Billy D. Buckler RLS on the township line between corners 1/2 mile south [M8] and 3 miles north [M1]. Set 1" pipe with 4" brass cap. 12" H.Maple N61°E 16 links, 15" H.Maple S45°E 54 links, 14" H.Maple S76°W 60 links.

Reestablished by Billy D. Buckler RLS on line between 1/4 cor. 1/2 mile north and 1/4 cor. 1/2 mile south along township line. Set 1/2"x18" iron bar buried in north shoulder of road. 13" Elm N36°E

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (M9) Found the 1958 monument as described, in good condition 8" below ground level in the north shoulder of an E-W road, at record bearing and distance from the H.Maple NBT N69°W, now dead. The NBT Elm N36°E was not found. Accepted the monument as a careful and faithful reestablishment of the position of the corner.
- (M7) The 1958 monument was recovered disturbed by heavy equipment and out of position. Remonumented the 1958 position at record bearing and distance from the stump remains of the remaining two 1958 NBTs. Applying the method used in 1958 to M1 and M8 as coordinated this date, the position for the corner was found 5.77' north and 3.48' west of the 1958 position of record and is accepted as a careful and faithful reestablishment of the position of the corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M9) Found 1/2" iron bar 8" b.g. in road shoulde Set measuring nail with MDNR tag in the side of: 8" Y.Birch S28°E 39.55' mrkd "S30 NBT" 11" Sugar S26°W 43.75' "S26 NBT" 10" Sugar N27°W 24.65' "S24 NBT" 9" Sugar N41°E 19.05' "S19 NBT" E= 8048790.736 N= 185234.376	(M7) Reset the 1958 monument, a 1"IDx36" I.pipe with 4" brass MI Dept. of Conservation cap.  Set measuring nail with MDNR tag in the side of 12" Sugar N55°W 44.85' mrkd "S13 NBT" 18" Sugar N10°W 37.85' "S13 NBT" 14" Sugar S30°E 29.05' "S19 NBT" 13" Sugar S30°W 49.1' "S24 NBT" E= 8048777.932 N= 186844.431
---	---

Bearings are magnetic.	Coordinates	are MCS83 in meters	(NAD83 (2011) Datum,
Coord. Ref.=NGS	PID DJ8902 :	N= 177197.949 m. E=	8027768.701 m.
4			

Signed by Stephen & maylest

20 links, 14" H.Maple N69°W 64 links.

Date

03/17/2015

FORM APPROVED BY MICHIGAN STATE BOAR

burveyor's Michigan License No

33986

For the Michigan Department of Natural Resources, Forest Resources Division

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
NO.
33986
STEPHAN J.
SURVEYOR
NO.
SURVEYOR

Revised Jan., 1983 Revised Oct., 1995