## DEC 2 7 1999

A WARA TOWN

For o	corners	in
-------	---------	----

record.

SECTION

## LAND CORNER RECORDATION CERTIFICATE

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of
Peer Group Under Act 345 of P.A. of 1990 On 12-P19 99
March 14 Hallan

4		W	lar	lao	2
Cha	airma	n			

	Filing Requir	ement of Act 74, Mich. P.A	l. 1970	Chairman		
Alger	Located In:	Corner Code #			05-	16
(County)				التاليون		
Public Land Survey	T 48N R 15W	<del></del>	TIME	1:30	pm.	
	T <u>49N R 15W</u> T R		1	DEC 1 5 19	99	
	T R ST R ST R		DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI			
	S T R				•	
	S T R		Register of De	eds Stamp & F	-ile Number	
4. Lot No, Reco	a field survey on Juments of P.A. 74, Michigan Pormance with regulations and the United States Department out of Law and/or that the content rules of the Michigan E	ALLY 01, 1999, 19	ioned 6 18—18—14 and 8—19—15 by a 9—15	C D E F G 5 - 4	H	12—13—13—24—1—25—25—
NOTE: Not more than 2 corner on this certificate.	s, all in the same town an	d range, may be recorded	12 31	32 33-	-34 - 35	<del>-36-</del>
A. Description of original mon D1: PLS * John Burt, DS, 1841 C.C.I. Co., Land Corner Record * Witnesses: W.Pine 12', N.85. Conservation, Forestry Divisio Brotherton, RLS. * 2 original links. * 12' W.Pine, N.85 W.,	. * Set quarter section p . * Ray J. Brotherton, RL 5 W., 81.5 links. * W.Pin n. * Dean C. DeLaMater, R BT's still in place, in g	ost. * W.Pine 28°, N.19 E., 26 S, 1952. * Found stumps of bot e 12°, S.53E., 92 links. * Unr LS, 1954. * Corner had been pr bood condition. * Set 1° iron p	links. * W.Pine 16 h original pine BT's ecorded. ***** Michi eviously located and ipe with 4° brass ca	s. * No corner igan Department d perpetuated b ap. * 12" W.Pin	material giv of by Ray J. e, S.50 E	ven.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: D1: Located corner search area by calculated position and standard field survey methods. Found 1' iron pipe with 4' brass cap and only 1 BT of the 1954 report. Stumps of the original BT's are still evident, in poor condition. Established additional reference trees. Corner monument as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D1: Existing 1" iron pipe with 4" brass cap. \* Renewed existing and established additional reference trees with BT signs, blazed, scribed and painted. \* Set PK nails with aluminum I.D. washers for measure in the following: R.Pine 7°, S.31 E., 47.98 feet, "1/4s BT". \* W.Pine 6°, N.40 E., 19.64 feet, "1/4s BT". \* R.Pine 5°, S.58 W., 16.55 feet, "1/4s BT". \* Existing - W.Pine 36°, N.80 W., 54.00 feet, "1/4s BT". \* Survey marker sign on 6 foot steel post, S.11 W., 1.6 feet. \* All bearings are magnetic.

Surveyor's Michigan License No.

ROBERT L. **JAMROS** PROFESSIONAL SURVEYOR Nø.99 25849 POFESSIONA