A PURVEY &

nec 2 7 1999

	•	
For corners in		

Alger

LAND CORNER RECORDATION CERTIFIC

P.A. of 1990 On 12-8 1999
Gueld Walson
Chairman

Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 cf

SECTION

Filing Requirement of Act 74, Mich. P.A. 1

Corner Code #

ATE 970	Chairman		
	05-155		
	FILED		
	TIME //38 PM		
	DEC 1 5 1999		

T 48N R 15W MC A11 B11 Public Land Survey 2. Property Controlling

DONALD W. KINNUNEN e Number

3. Miscellaneous S T R	REGISTER OF DEED ALGER COUNTY, M gister of Deeds Stamp & File	
4. Lot No, Recorded Plat 5. Private Claims	- A B C D E F G	1
Robert L. Jamros, in a field survey on October 28, 1999, 19,	3 4 7 8 9 - 1	-
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land	6 18 17 16 1	5
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, as expressed below:	8 19 20 21 2 9 10 30 29 28 2	7

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC2: PLS * George E. Adair, DS, 1851. * 10.77 chains over lake by meanders, set post at meander corner. * W.Pine 30*, N.19 W., 30 links. * W.Pine 13", 5.50 E.,55 links. ***** C.C.I.Co., Land and Timber Dept. * R.J. Brotherton, RLS, 1952. * Ran from 1/4 corner East and 1/4 corner North and West, set at 25.50 chains. * Set 5" W.Pine post. * 6" W. Birch, S.45 E., 6 links; * 8" W.Pine, N.64 W., 7 links. * Unrecorded. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC2: Located corner search area by calculated position and standard field survey. Found old concrete monument and survey iron on section line at top of East bank of Nevin's Lake. Established corner position on section line at proportionate distance between 1/4 section corner to the East and section line to the West. Located a decayed 20° W.Pine stump at GLO BT position of 5.50 E., 55 links. Condition of W.Pine stump makes GLO marks unidentifiable. Set monument at established calculated position. Corner position as established is accepted as a careful and faithful reestablishement of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC2: Set 2 1/2"x30" Berntsen aluminum monument No. A1NB30 with 3 1/4" aluminum cap stamped to identify corner position. * Established the following reference trees with BT signs, lower blazes, scribed and painted. * Set PK nails with aluminum I.D. washers for measure in the following: Y.Birch 10', S.80E., 18.85 feet, "BT". * W.Pine 11", N.25 E., 27.70 feet, "BT". * W.Pine 18", S.20 E., 10.90 feet, "BT". * Survey marker sign on 6 foot steel post, N.68 E., 1.5 feet. * All bearings are magnetic.

Signed by_ Surveyor's Michigan Lice se No.

ROBERT L **JAMROS** PROFESSIONAL SURVEYOR No. OFESSION

OF MICH