Survey & **CNUMENTATION**

Located In:

A Q M

1 K M

JAN 182001

RECTION

Alger

(County)

LAND CORNER RECORDATION CERTIFICATE

Land Survey Remonumentation Peer Group Under Act 345 of
P.A. of 1990 On 12-13 \$ 2000 Mull Calson
Chairman

Jerse or newsparter County

_		
ŀαr	corners	ın

Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #	05-208
į	FILED
D07	TIME 8:50 AM.

1. Public Land Survey T R R B D07	TIME 8'SO ACL.
T R T R T R T R T R T R T R T R T R T R	DEC 20 2000 DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	A R C D E F G H J K L M
Robert L. Jamros, in a field survey on April 18 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentione in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the currer manual of survey instructions of the United States Department of the Interior, Bureau of Lan Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a Court of Law; established, re-established, monumented, recovered, foun as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration:	nt 7

po7: PLS Geo. E. Adair, DS, 1851. Set quarter section post. W. Pine 28", quarter section post. W. Pine 30", N.20°W., 12 links. W. Pine 28", S.30°E., 18 links. **** Michigan Department of Conservation, Forestry Division. Dean C. DeLaMater, RLS, 1953. Set 1" iron pipe with 4" brass cap in center of 30" W. Pine stump. 2 original BT's still in place, 1 good, 1 poor. W. Pine stump 30", N.19°W., 14 links. W. Pine stump 24", S.29°E., 45 links. Liber 2, Page 25, Alger County corner reports. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

25849

Monument and accessories of the 1953 report have all been lost (area site of grading operation). Established corner position at midpoint and on line between section corners and is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D07: Set 2½" x 30" Berntsen aluminum monument no. AlNB30 with 3½" aluminum cap stamped to identify corner position. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: R. Pine 14", N.46°E., 32.38 feet (45 BT); W. Pine 8", S.56°E., 34.57 feet (45 BT); R. Pine 12", S.64°W., 34.35 feet (4S BT); W. Pine 4", N.62°W., 8.35 feet (4S BT). Survey marker sign on 6 foot steel post. S.52°E., 1.0 feet. All bearings are magnetic. TE OF MICH

> ROBERT L. **JAMROS** PROFESSIONAL SURVEYOR No. 25849 OFESSIONEL

Signed by_

Surveyor's Michigan License No.