

JAN 18 2001

Approved by Alger County
Land Survey Re-monumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000
Donald W. Kinnunen
Chairman

For corners in **SECTION** **LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

<u>Alger</u> (County)	Located In:	Corner Code #
	48N 15W	L07
1. Public Land Survey	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
4. Lot No. <u> </u> , Recorded Plat <u> </u>		
5. Private Claims <u> </u>		

FILED
TIME 8:50 Am.

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI
Register of Deeds Stamp & File Number

05-217

I, Robert L. Jamros, in a field survey on October 20, 2000
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, recovered, found
as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

L07: PLS Geo. E. Adair, DS, 1851. Set quarter section post. Hemlock 12", South, 19 links.
W. Pine 10", N.45°W., 13 links. ***** C.C.I. Co. Ray J. Brotherton, RLS, 1949. A traverse
by transit was run connecting section corners on the line between 13 and 24. At midpoint set
new 5" cedar post and iron. No Government BT's were found. No new references were made.
Unrecorded report of 1964. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L07: Established corner position at midpoint and on line between sections corners ½ mile
East and West. Found remains of 5" cedar post down and some distance from corner position,
iron was not found. Corner position is close to county dirt road and this area has been
graded for drainage purposes. Corner position as established is accepted as a careful and
faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L07: Set 2½" x 30" Berntsen aluminum monument no. A1NB30 with ¾" aluminum cap stamped to
identify corner position. Established reference trees with BT signs, blazed, scribed and
painted. Set PK nails for measure with aluminum I.D. washers in the following: Maple 10",
N.04°E., 18.51 feet (¼S BT); W. Pine 14", N.50°E., 32.75 feet (¼S BT); Spruce 10", S.75°E.,
15.35 feet (¼S BT); Spruce 9", S.89°W., 15.34 feet (¼S BT). Survey marker sign on 6 foot
steel post, S.09°W., 1.0 feet. All bearings are magnetic.

Signed by *Robert L. Jamros*
Surveyor's Michigan License No. 25849

Date Dec 17, 2000

