

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 48N R 33W	F7
2. Property Controlling in Section	S 16 T 48N R 33W	14
3. Miscellaneous Property in Sec.	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Stephan J. Szyszkoski, in a field survey on 14 10/13/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 16) South 1/16 corner between Sections 15 and 16. 1981 - Established by K.L.Sackett RLS
midway and on line between corners north and south. Set 1"IDx36" I.pipe with 4" alum. cap. 14"
W.Birch N72W 12.8', 6" Maple N06E 9.3', 16" Maple S61E 19.1'.

(F7) Quarter corner common to Sections 16 and 21. 1981 - Reestablished by K.L.Sackett RLS midway and
on line between corners east and west. Set 1"IDx32" Iron pipe with 4" alum. cap. 5" Balsam N12E
2.8', 10" Spruce N51W 19.7', 10" Balsam S20W 26.6', Squared a 3" Balsam South 2.2'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 16) Found the 1981 monument in good condition and at record bearing and distance from the
1981 witnesses. The W.Birch N72W and the Maple S61E are standing dead. The Maple N06E is in good
condition. Found the Quarter corner G6 to be 1317.44' north and the Section corner G7 to be 1315.27'
south and this 1/16 corner monument to be 0.77' west of a straight line between them. Accepted the
monument as a careful and faithful establishment of the position of the corner.

(F7) Found the 1981 monument in good condition and at record bearing and distance from the 1981
witnesses. The Spruce N51W and Balsam S20W are dead and down. The squared Balsam is windthrown.
The Balsam N12E is in good condition. Found the distance to Section corner G7 to be 2678.09' and the
distance to Section corner E7 to be 2683.00', this monument being 0.7' north of a straight line
between them. Accepted the monument as a careful and faithful reestablishment of the position of the
original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Fd. 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Maple N06E 9.35' old blazes 1981 BT
5" twin Maple S10W 4.0' mrkd "1/16S BT"
5" Balsam S69W 13.8' do
7" Spruce N51W 14.1' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(F7) Fd. 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Balsam N17E 3.1' old blazes 1981 NBT
7" Cherry N89W 66.95' mrkd "1/4S NBT"
5" Balsam N61W 55.8' do
5" Balsam N27W 19.8' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/12/2011

For the Michigan Department of Natural Resources and Environment, Forest Management Division



16586

16584