LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #	W	3
1. Public Land Survey	T 49N R 34W T 49N R 34W	F9		
2. Property Controlling in Section	S T R S T R	E9	ņ.	
3. Miscellaneous Property in Sec.	S T R S T R R S T R R		3	
4. Lot No. , Re-	corded Plat		* 0 -	Stamp & File Number FGKIJKLM
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6				
a court of Law and for that the	corner points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree	5 above were in conformance with		5 15 14 13
NOTE: Not more than 2 corner on this certificate.	ers, all in the same town and range, m		10 30 29 2 11 12 31 32 3	8 27 26 25 3 36 35 36
A Description of anisinal an			19	

- A. Description of original monument and accessories and/or subsequent restoration:
- (F9) Quarter corner common to Sections 21 and 28. 1853 Established by Francis Coleman Deputy Surveyor midway and on the Section line between Section corners 40.22 chains East and West. Set post. Y.Pine 20" N32E 19 links, S.Pine 12" S55W 22 links. 1958 - Remonumented by Billy D. Buckler RLS at record bearing and distance from probable B.T. Y.Pine bearing N32E 19 links, stump burned badly. I.pipe with 4" brass cap. Set 1"ID 13" R.Pine N65W 86 links, 12" R.Pine N48E 88 links. 1975 - K.L.Sackett RLS used the corner to subdivide Section 28, but took no additional witnesses.
- (E9) Corner common to Sections 20-21-28-29. 1958 Billy D. Buckler RLS remonumented the corner from numerous blazes in vicinity and swamp edge 50 links to west. Found Jack Pine bearing S46E 35 links scribed "R34WT49N", marked many years ago. Set 1" pipe with 4" brass cap. 8" J.Pine N39W 43 links, 6" J. Pine \$34W 47 links.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (F9) The 1958 monument and accessories were not recovered and appear to have been destroyed. No direct evidence of the corner position was found on the ground. Reestablished the 1958 position using the field notes of the 1975 subdivision by K.L.Sackett, at Mr. Sackett's distance, indexed, north of F10 and on a prolongation of a straight line from F11 through F10.
- (E9) Found the 1958 monument in good condition and at record bearing and distance from the 1958 NBT J.Pine N39W 43 links, now a dead, leaning stub. The other 1958 NBT is gone. Accepted the monument as the best available evidence of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set 4"x4" cedar post N07°E 0.8'. The corner position falls in a plowed field and no other accessories are available. MCS83 bearing and grid distances to: $G9 = S88^{\circ}07'51''E 2634.87' (2635.24' ground)$ E9 = N88°29'21"W 2644.30' (2644.67' ground) E=7880238.381 N=205526.796

(E9) Found 1"ID I.pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:

N=205548.046

12" J. Pine N48°E 3.25' mrkd "S21 NBT" 6" W.Birch S37°E 23.65' "S28 NBT" 4" R.Pine S75°W 13.15' "\$29 NBT" 6" Maple N50°W 25.55' "S20 NBT" Set sq'd Cedar post adjacent. E=7879432.679

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum) Signed by Date 03/13/2013 Surveyor's Michigan License No. For the Michigan Department of Natural Resources, Forest Resources Division

OF MICHIGA STEPHAN J SZYSZKOSKI LAND SURVEYOR FORM APPROVED BY MICHIGAN STATE BOARD OF P