LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF	- :	LOCATED I	N:	CORNER	CODE NUMBER	
1. PUBLIC LAND	SURVEY	T. 50 N	., R. 34 W	: G1 8	. I1	
2. PROPERTY CO	ONTROLL- SECTION———	,T N	i., R E.	:		·
3. MISCELLANEO PROPERTY IN	SECTION	,T S	i., R E.			
4. LOT NO	, RECO	RDED PLAT				
5. PRIVATE CLA	IMS					REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points re-established, me and rules therefor Bureau of Land Mand 5 above were	mentioned in lin onumented, re-m re as required in Management or b , in a field survey w and in conform	es 1 and 2 ab conumented, r the current r by a decree of	ove were, in a recovered or manual of surv a court of lav	a field survey restored as ex vey instruction w. Furthermo _, 19, for	on see below and pressed below and ans of the United Sore, that the corner and, recovered, rest	of P.A. 74, Michigan P.A. of 1970, w
A. Description o	f original monum	nent and acce	ssories and/or	r subsequent 1	estoration:	
Corner Gl	Sugar pos Hemlock Lynn	st c 30 S48W 20 S34E	(Not ! 34 (" ! 18 ("	t found.	No subsequent	subsequent monument.) accessories found.) accessories found.)
	Maple pos Hemlock Maple	st c 8 S52W 5 S25E	(Not ! 41 (" : 27 ("	t found.	No subsequent	subsequent monument.) accessories found.) accessories found.)
Corner G1: road while named Schwal 9.1 lks. E of to be well of E to standar Corner I1: corners 74.6 ft. and Nor	On 4/10/73 making a retain. Method of the computation the large stablishes of the large stablishes of the large stablishes but thern Paper	witnessed racement of settinuted propolimits of mer is 4.1 shed 5/6/7 at 7.483 c	a monumer survey in g the correctionate probabilition for the correction for the correction posts and the correction posts are corrected posts and the correction posts and the correction posts and the correction posts are corrected posts and the correction posts are corrected posts and the correction posts are corrected posts and the correction posts are corrected posts and the correction posts and the correction posts are corrected posts and the correction posts and the correction posts are corrected post	nt describ this twp ner is unl position of ty as to of he record ionately of und rotted ter on a se	Possibly seconown, but it on the 5th Cororiginal established being 4.10 chon 5th Correct remnants of nearby tree.	w, found in an E & W county et by a former local surveyor falls only 12.5 lks. S and crection Line, which seems olishment. Distance
Corner G1: 3/4" square iron pin, length unknown, buried in road. NE corner of garage S39°E (mag.) 46.6 ft. Nail in Power Pole S50°W (mag.) 44.06 ft. Nail in Sugar Maple 26 N20°W (mag.) 70.04 ft.						
Corner II: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap. Red Maple 5 S42°W (mag.) 6.3 ft. "S3, NBT" Red Maple 4 S53°E (mag.) 9.8 ft. "S2, NBT"						
SIGNED BY			<u> </u>		DATE	
SURVEYOR'S M	ICHIGAN REG	ISTRATION	NO			(SEAL)
FOR STATE AN	D UNITED ST.	ATES AGEN	CIES:			THE OF MICHELLE
SIGNED BY		CHIEF OF SURV	Zv matry C		DATE	O ENGER *
APPROVED AN		MICHIE	Thur O. GAN REGISTERED Arthur O.	Enger		Oceober 19 1976 * = SURVEYOR NO 13581 LAND SURVEYOR AND LAND SURVEYOR SURVEYOR AND LAND SURVEYOR SURVEYOR SURVEYOR SURVEYOR SURVEYOR SURVEYOR SURVEYOR SURVE
SURVEYOR'S M		•			l Resources	CARED LAND SUMMEN
SURVEYOR'S M	ICHIGAN REG	MOLLANTEL	140			