

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>50</u> N. <u>34</u> E. <u>W.</u>	<u>17</u>
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. _____ E. _____ S. _____ R. _____ W. _____	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. _____ E. _____ S. _____ R. _____ W. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		
		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 12, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Sec. Corner 14, 15, 22, & 23, T50N, R34W:
Hemlock post (Not found. No subsequent monuments found.)
Hemlock 14 N28W 19 (Not found. No subsequent accessories found.)
Y. Birch 12 S20E 17 (" " " " " ")

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner re-established at intersection of true line between sec. cor. 78.67 ch. W and 78.68 ch. E and true line between sec. cor. 78.56 ch. S and 160.38 ch. N. Found this to be most consistent with original field note calls to natural objects. By experience, I found that distances given in field notes are somewhat unreliable, probably because of the sharply hilly nature of the terrain. If this corner were placed any further N, the line between Sec. 15 & 22 would not cross the "bog 3 ch. in dia. mostly S of line", as stated in original notes. West side of bog is 23.88 ch. W of this corner, although the original random line notes indicate a distance of 19.55 ch.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Red Maple 7 N45°W (mag.) 7.0 ft. "S15, NBT"
Red Maple 8 S21°W (mag.) 11.6 ft. "S22, NBT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE October 25, 1976

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

