## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	_ Located In:	Corner Code #		
1. Public Land Survey	T 50N R 34W	K5 (GCDB 600500)		
2. Property Controlling in Section	T 50N R 34W S T R S T R	(GCDB 500540)		
3. Miscellaneous Property in Sec.	S T R S T R		Periotes of People Start	
4. Lot No. Red 5. Private Claims	corded Plat		Register of Deeds Stamp 8	H I J K L M
	K5	12/08/15	2 - 6 - 5 - 1 - 4 - 1	3
	74, Michigan P.A. of 1970, the corne	12/09/15 do hereby state er points mentioned in lines 1 and 2		10—11—12
instructions of the United States I	Department of the Interior, Bureau of	uired in the current manual of survey Land Management or by a decree of and 5 above were in conformance with	of 6 18 17 16	
the rules of the Michigan Board re-established, monumented, recover		ee of a Court of Law; established,	9 20 21	22 23 24
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and ran	ge, may be recorded	10 30 29 28 11 12 31 32 33	27——26——25—— 34——35——36——
A. Description of original m	onument and accessories and/o	or subsequent restorations	13	

- (K5) Corner common to Sections 11-12-13-14. 1849 - Established by Wm.Burt, Deputy. Set Sugar post. Hemlock 14" N51°E 32 links, Y.Birch 20" S42°W 19 links. Found no subsequent record.
- (I4) Quarter corner common to Sections 10 and 11. 1849 Established by Wm.Burt, Deputy, midway and on the Section line between Section corners 40.00 chains north and south. Set Sugar post. Y.Birch 8" N65°W 22 links, Hemlock 8" S42°E 42 links. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K5) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner by double proportionate measurement to the original record between monumented Section corners 5302.52' north, 5229.23' east, 5302.38' south, and 10480.42' west.
- (I4) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2622.80' north and south.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K5) Set 1"IDx28" I.pipe with 2" Set measuring nail with MDNR tag 12" Maple N72°E 2.4' mrkd 7" twin Sugar S37°W 13.3'	in the side of:		tag in the side of: mrkd "1/4S NBT"
9" Sugar N79°W 27.0'	"S11 NBT"	7" Sugar S52°E 24.1' 5" W.Pine S53°W 31.9'	do
10" Poplar N32°W 9.95'	"S11 NBT"	3" W.Birch N43°W 17.7'	do do
Set sq'd cedar post adjacent.		Set sq'd cedar post adjacent.	
E= 7884536.398 N= 218233.586		E= 7882941.400 N= 219070.49	

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum Coord. Ref.=NGS PID D08499: N= 221257.621 m. E= 7884435.168 m.

Signed by Surveyor's Michigan License No. 33986

Date 01/21/2016

For the Michigan Department of Natural Resources, Forest Resources Division

SURVEYOR FORM APPROVED BY MICHIGAN STATE BOARD

STEPHAN YSZKOSK

LAND