## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For comers in

Baraga (County)	_ Located In:	Corner Code #			
1. Public Land Survey	T 51N R 32W	19			
2. Property Controlling in Section	T R S T R S 22 T 51N R 32W	14			
3. Miscellaneous Property in Sec.	S T R S T R				
4. Lot No. , Re 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number	-	
	19 03	3/21/2011	<b>₽</b> ├────────────────────────────────────	_	
that under requirements of P.A. above were in conformance with	n a field survey on 14 03 74, Michigan P.A. of 1970, the corneregulations and rules therefore as req	3/21/2011 do hereby state er points mentioned in lines 1 and uired in the current manual of surve	24 - 7 - 6 - 9 - 10 - 12 - 12	_	
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7					
the rules of the Michigan Boar re-established, monumented, recov	rd of Land Surveyors or by a Decre	and 5 above were in conformance wit see of a Court of Law; established	ith 7 ad, 8 19 20 21 22 23 24	-	
	ners, all in the same town and ran	ge, may be recorded	10 30 29 28 27 26 25 11	_	
on this certificate.			12 31 32 33 34 35 36		
				***	

## A. Description of original monument and accessories and/or subsequent restoration:

(I9) Corner common to Sections 22-23-26-27. 1982 - K.L.Sackett RLS restored the corner at a found 1"ID iron pipe, believed to have been set by Norman T. Thompson RLS. Set 1"IDx32" I.pipe with 4" alum. MDNR cap. 8" Sugar S31E 6.7', 5" Sugar N27E 21.0', 5" Sugar N75W 21.2'. 1986 - The 1982 monument was found and accepted by the U.S. D.O.I., Bureau of Land Management Cadastral Surveyor Stephen D. Douglas during his dependent resurvey of this township. The 1982 NBTs are noted in the BLM field notes: Maple 6" N28E 33 links, Maple 10" S29E 11 links, Maple 6" N74W 33 links.

(14-Sec. 22) South 1/16 corner between Sections 22 and 23. Not established in the original survey.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I9) Found the 1982 monument in good condition and at record bearing and distance from the 1982 NBTs S31E and N27E, in good condition, found with measuring nail and washer stamped "PS 24591" facing the monument. Accepted the monument as the best available evidence of the position of the original corner.

(14-Sec. 22) Established the corner midway and on the Section line between Section corner 1316.89' south and Quarter corner 1316.89' north. From the position for the corner, I found a 3/4" iron pipe, not of record S26W 2.1', not accepted as marking the position for the corner.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I9) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 11" Sugar S23E 6.85' old blazes (1982 NBT) 6" Sugar N31E 21.5' do 5" Sugar N36W 9.4' mrkd "S22 NBT" 6" Sugar S88E 11.15' "S26 NBT" Set sq'd Cedar post adjacent. Bearings are magnetic.

(14) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 11" Maple N23E 37.9' mrkd "1/16S BT" 9" Y.Birch S75E 25.95' do 6" Sugar S02W 31.3' do 9" Sugar S60W 21.25' do Set sq'd Cedar post adjacent.

Signed by Stshu	I Synshol.	Date	08/30/2011
Surveyor's Michigan License No.	33986		

For the Michigan Department of Natural Resources, Forest Management Division

16713 16712 FORM APPROVED BY MICHIGAN STATE BOARD

Bearings are magnetic.

CAND SOL Rervised Oct., 1995

STEPHAN J

YSZKOSK

LAND

SURVEYOR