LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #			6
(County)	P ²		E		
1. Public Land Survey	T 52N R 30W T 52N R 30W	K10			15
2. Property Controlling in Section	S T R		11"		
3. Miscellaneous Property in Sec.	S T R S T R		_		
4. Lot No. Rec 5. Private Claims	corded Plat	10/0044	Register of De	eeds Stamp & File Nu EFG Я I	J K L M
above were in conformance with r instructions of the United States D	a field survey on 19 04/17, Michigan P.A. of 1970, the corner regulations and rules therefore as require Department of the Interior, Bureau of La	ed in the current manual of survey and Management or by a decree of	5 18 17	16 15	1112-
the rules of the Michigan Board re-established, monumented, recove	¥	of a Court of Law; established,	7 6 19 20 9	21 22	24
NOTE: Not more than 2 corne on this certificate.	ers, all in the same town and range,	may be recorded	11 32 32	33 34	35-36-

A. Description of original monument and accessories and/or subsequent restoration:

(K10) Quarter corner common to Sections 25-26. 1846 - Established by Wm. Ives Deputy Surveyor. Set post midway and on the Section line between Section corners 40.00 chains north and south. Hemlock 16" S85E 04 links, Ironwood 8" S71W 18 links. Found no subsequent record.

(I9) Corner common to Sections 22-23-26-27. 1846 - Established by Wm. Ives Deputy Surveyor. Set post. Y.Pine 22" S31W 21 links, Spruce 12" N49E 16 links. 1940 - Norman T. Thompson RLS ran a random line from Ill north between Sections 26 and 27. He found the 1/4 corner Il0 6' east of his line and the Section corner I9 6' west of his line. At I9 he states "Pine stump 24" old notch in, set balsam post".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K10) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner position midway and on the Section line between Section corners 2637.73' north and south.

(I9) The original post and accessories were not recovered. The 1940 balsam post was not recovered. Found a milled triangular post, approx. 7" wide faces x 4 ft. high, scribed to identify the corner, rotted at base. The position of the post is in substantial accord with the original record to monumented corners east and south and agrees well in relation to 1/4 corner I10 with respect to Norman T. Thompson's offset measurements noted above. I accept the post as the best available evidence of the position of the original corner. Replaced the post with a new monument, described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 12" Hemlock N62E 24.2' mrkd "1/4S NBT" 4" Sugar S30E 16.3' do 5" Y.Birch S77W 26.1' do 5" Ironwood N39W 7.25' do Set sq'd Sugar post adjacent. Bearings are magnetic.

(I9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 12" Maple N68E 15.2' mrkd "S23 NBT" 18" W.Pine S51E 23.25' "S26 NBT" 10" Hemlock S84W 9.5' "S27 NBT" 11" Sugar N70W 7.9' "S22 NBT"

Set sq'd cedar post adjacent. Bearings are magnetic.

Signed by Acade Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Management Division

16607 16608 FORM APPROVED BY MICHIGAN STATE BOARD

AND Selection 14, 1975

Larised Jan., 1983

Rervised Oct., 1995

STEPHAN J

LAND SURVEYOR

YSZKOSK