fitte.	Process of the second	16 00 - 1			
KAINED BY THE BERNIER CO	UNTY	X.	- arcoi	RDEO	
SURVEY PEER GROUP AS TH DEFICIAL CORNER UNDER MICH	ትይ HGAN				
OFFICIAL CORNER UNDER MICH PUBLIS ACT 245 OF 1990					
Sidena	Berrien (County Remonumentati ER RECORDATION CERT	on Teicate() NOV - 1	AM In: 39	
12-77-00		ement of Act 74, Mich. P	A 1970		
For corners in			RÉGISTER (OF DEEDS	
Berrien (County)	_ Located In:	Corner Code ≠	SEARIEN COUN	TY, MICHIGAN	
t-county)					
 Public Land Survèy 	T 5S R 19W	<u> </u>			
	T R T R				
	T R		11/01/00	111#5437	A44
2. Property Controlling	S R			CURNER	\$9.00
in Section 3. Miscellaneous	S T R S T R		11/01/00 Register of Deed	111#5437 Js Stántó & Éitéinúi	644 66-42 00
Property in Sec.	S T R		Register of Deet	inwesters distance	
4. Lot No, Rec	and Disk				
5. Private Claims	corded Plat		A B C	DEFGHIJ	K L M
			2 6	\$ -\- \$ -\- \$	2-1-1-1
			3	8-10-0-1	
Charles W. Barger	in a field survey onSer	orember 💢 20	000 5		
do hereby certify that under requi	irements of P.A. 74, Michigan P.A.	of 1970, the corner points ment	ioned 6 18	17 16 15 1	4-13-
current manual of survey instruct	tions of the United States Depar	rtment of the Interior, Bureau of	Land /	┤╴┠╸╏ ╴ ╏╸ ╏	
Management or by a decree of a C above were in conformance with	the rules of the Michigan Board	of Land Surveyors or by a Decre	eofa	20 21 22 2	3 - 24
Court of Law; established, re- expressed below:	established, monumented, re-	monumented, recovered, four	nd as	29 - 28 - 27	2625
NOTE: Not more than 4 cor	mers, all in the same town a	nd range, may be recorded	11		╁╌╂╌┼╌┤
on this certificate.			12 31-	3 2 33 34 -	35 -36
A. Description of original mo	onument and accessories an	nd/or subsequent restoration	13 <u> </u>	 	
,					
Feb 183		st 18 S45E 12			
20 2,0.		N5W 25			
				•	
		•			
			•		
B. Description of corner evi	dence found and/or method	applied in restoring or rees	tablishing corner;	-	
July 20	000 Found	3/4" Iron in Monumer	at Roy		
C. Bar		PP N56d06'W 67.97'			
·	PK in	PP N36d34'E 53.26'			
		PP S43d55'E 44.90' N38dW 52.03'	•		
	nyde .	nyoun yrios			
•		,			
		,			
				(Abo paumar)	
 C. Description of monumen 	nt for corner and accessories	established to perpetuate	locating the position of	the comer:	
1-4	1" Pipe 36" Long wit	h 2½" Remonumentatio	on Brass Cap in 1	Monument Box	
•	Witnes	s Tag in PP N56d06'	'W 67.97'	AND OF MICHE	
		s Tag in PP N36d34' s Tag in PP S43d55'		ALE CANO	44
		N38dW 52.03	A 44.70	CHARLES W.	
•	•		A TOTAL SERVER	HAND SURVEYOR	¥Ē
	ACCEPTED AS A CAREF ORIGINAL CORNER.	UL AND FAITHFUL PEKT	TETOWITON OR THE	31589	ran.
VI 1118	- ALL O LABOR OF PARKET		E.	CENSON WELL	113
_				LAND SUNTER	. ,
Giand by Pharles &	WBayer P.S.	Date	OCTOBER 26, 200	0	
SIGNED BY SURVEY &	No. 31589		FORM APPROVED BY MICHIGAN S	STATE ROADD OF LAND SURVEYO	RS, JAN. 28, 1971
REMONITMENTA	TION		FURN AFFRUSED OF MICHOLA	. REYII	SED MAY 14, 1975 EVISED JAN., 1983

JAN 3 1 2001

LIBER 4

PAGE 232

SECTION

2000 Berrien County Remonumentation Barger Engineering, Inc.

WEST QUARTER CORNER SECTION 11, T5S, R19W EAST QUARTER CORNER SECTION 10, T5S, R19W I-4

Feb. 1830

Set Post

L. Lyons

W Oak 18 S45E 12

Do 20 N5W 25

Feb. 1876 T. Love Pine Stump 20 N5W 25 (originally called W. Ash)

1954

Berrien Co. Rd Comm

12" Maple N45W 36.5 to Center

2" Pear S45W 38.5' to Center 3" Pear S60E 48.5' to Center

3" Cedar N45E 48.5' to Center

1973

Set Iron

Berrien Co. Rd Comm

TP S45E 44.45'
TP S40E 56.85'

Top Bolt of Hydt N30W 65.0'

(additional available)

Apr 1987

Survey

K. Kamer

Found 1/2" Iron Pipe in Monument Box

PK in PP S45E 44.92' PK in PP N40E 53.2' PK in PP N45W 67.9'

Cent Top Bolt in Hydt N30W 48.22'

Apr 1989

Recorded Survey L1422 P401

R. Harner No Tie Downs

Mar 1991

Survey

J. Kamer

Found 1/2" Iron Pipe in Monument Box Cent Top Bolt in Hydt N30W 48.22'

PK in PP S45W 44.92' PK in PP N40E 53.2' PK in PP N45W 67.9'

Jun 1999

Survey

J. Kamer

Found 3/4" Pin in Monument Box

PP N55W 67.79'
Cent Hydt N38W 52.06'
PP N36E 52.76'

PP S45E 44.9'

Jul 2000 C. Barger Found 3/4" Iron in Monument Box

PK in PP N56d06'W 67.97 PK in PP N36d34'E 53.26'

PK in PP S43d55'E 44.90' Hydt N38dW 52.03' JAN 31 2001

SURVEY & REMONUMENTATION

SECTION

Barger Engineering, Inc. 20249.03

LIBER 4

PAGE 233