LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 Chippewa Co. 3 Corners.

I-11 Sec. Cor. 26-27-34-35. Fir 10, N30°W, 9 1ks. & Fir 8, S22°E, 13 1ks. 10-Sec.24 South 1/16 corner on west side of section 24. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Re-established corner midway and on line bet. two sec. core. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Placed corner midway bet. section corner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76°E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Pine, N58°W, 48.9'. I-11 8" Cedar, N35°E, 5.0' & 6" Cedar, S85°W, 35.9' & 10" Cedar, S43°E, 26.3'. 10-Sec.24 6" Cedar, N44°W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22°W, 4.9' & Corner lies 33' South of road. SIGNED BY BILLY D. Buckler SURVEYOR MICHIGAN REGISTRATION NO. 2887 DATE DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY CHIEF OF SURVEY PARTY DATE	2. PROPERTY CONTROLL: NG IN SECTION. 1. MSCELLANBOUS 3. MSCELLANBOUS 4. LOT NO. 7. RECORDED PLAT 5. PRIVATE CLAIMS MORE PROPERTY IN SECTION. 7. RECORDED PLAT 5. PRIVATE CLAIMS MORE PROPERTY IN SECTION. 7. RECORDED PLAT 8. R. S. S. S. PRIVATE CLAIMS 1. Billy D. Buckler 1. Billy D. Buckler 1. Billy D. Buckler 1. Description of original monumented, resourced or restored as represent below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interest of a count of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on. Bureau of Land Management or by a deriver of a count of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on. Bureau of Land Management or by a deriver of a count of law. A. Description of original monument and accessories and/or subsequent rectorations. Quarter & sec. cor. set by John Mullett, D.S. in 1845. Bearings were: D-7 Querter Cor. bet. Sec's. 17-20. Spruce 1A, N31°2, 15 lks. & Suger 10, South, 20 lks 1-11 Sec. Gor. 26-27-34-35. Fir 10, N30°M, 9 lks. & Fir 8, S22°E, 13 lks. 10-Sec.24, South 1/16 corner on west side of section 24. B. Description of corner evidence found and/or method applied in rectoring or re-establishing corner: Re-established corner midway and on line bet. twe sec. core. 1-11 Re-established corner midway and on line bet. twe sec. core. 1-24 Re-established corner midway bet. section cerner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1-2 No. Birch, S76°E, 35.9° & 8° Tvin Oak, N3°M, 52.2° & 6° M. Pine, N58°M, 48.9°. 1-11 8° Cedar, N35°D, 5.0° & 6° Tvin Oak, N3°M, 52.2° & 6° M. Pine, N58°M, 48.9°. 1-11 8° Cedar, N44°M, 4.1° 8° T° Gedar, Nest, 20.7° & 8° Cedar, S22°M, 4.9° & Corner lies 33° South of rosa. SIGNED BY Billy D. Buckler SIGNED BY Bill	F	OR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	1
3. MISCRELAMBOUS PROPERTY IN SECTION	ALOT NO	1.	PUBLIC LAND SURVEY	т. <u>42 ^{N.}, R. 2 E.</u>	D-7, I-11	
## LOT NO	ALOTNO	2.	PROPERTY CONTROLL- 24	,T. 42 N. R. 2 E.	10-Sec. 24	
Billy D. Buckler 1. Billy D. Buckler 1. Billy D. Buckler 1. Control points mentioned in lines 1 and 2 above were, in a field survey on 10-12 & 8-32 1. D. T. Stabilished, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Dureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 3 above were, in a field survey on. 19. found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law. A. Description of original monument and accessories and/or subsequent restoration: A. Description of original monument and accessories and/or subsequent restoration: Quarter & sec. cor. set by John Mullett, D.S. in 1845. Bearings were: D-7 Quarter Cor. bet. Sec's. 17-20. Spruce 14, M31°A, 15 lks. & Sugar 10, South, 20 lks 1-11 Sec. Cor. 26-27-34-35. Fir 10, N30°N, 9 lks. & Fir 8, S22°E, 13 lks. 10-Sec.24 South 1/16 corner on west side of section 24. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: D-7 Re-established corner midway and on line bet. two sec. cors. 1-11 Re-established corner midway and on line bet. two sec. cors. 1-12 Re-established corner midway and on line bet. two sec. cors. 1-13 Placed corner midway bet. section corners in four directions. 10-Sec.24 Placed corner midway bet. section corners to South and ‡ corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminum cap at all corners. New Bearings are: 10-Sec.24 6" Cedar, Nac's, 5.0° & 6" Cedar, S85°N, 35.9° & 10" Cedar, Sk3°E, 26.3°. 10-Sec.24 6" Cedar, Nac's, 5.0° & 6" Cedar, S85°N, 35.9° & 10" Cedar, S22°N,	S. PRIVATE CLAIMS [B111y D. Buckler] [I, B111y D. Buckler] [I, B1	3.	MISCELLANEOUS PROPERTY IN SECTION	,T N., R E.		, ,
Billy D. Buckler 1. Buckler 1. Billy D. Buckler 1. Billy D. Buckler 1. Billy D. Buckler 1. Buckler 1. Billy D. Buckler 1. Billy D. Buckler 1. Buckler 1. Billy D. Buckler 1. Buckler 1. Billy D. Buckler 1. Buckler 1. Buckler 1. Billy D. Buckler 1. Buckler 1. Buckler 1. Billy D. Buckler 1.	Billy D. Buckler Billy D. Buckler	4.	LOT NO, RECO			
Billy D. Buckler Description of corner evidence found and/or method applied in restoring or re-establishing corner: Description of corner evidence found and/or method applied in restoring or re-establishing corner: Description of corner evidence found and/or method applied in restoring or re-establishing corner: Description of corner midway bet. section 24. Description of monument and and/or method applied in restoring or re-establishing corner: Description of corner evidence found and/or method applied in restoring or re-establishing corner: Description of corner midway bet. section 24. Description of corner midway bet. section 24. Description of monument found and/or method applied in restoring or re-establishing corner: Description of corner evidence found and/or method applied in restoring or re-establishing corner: Description of corner evidence found and/or method applied in restoring or re-establishing corner: Description of corner midway bet. section cerner to South and the corner to North. Description of monument for corner midway and on line bet. two sec. cors.	Billy D. Buckler the corner points mentioned in lines 1 and 2 above were, in a field survey on 10-1 & 8-13 19.79, established, momented, resonanced or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the linterior. Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on	5.	PRIVATE CLAIMS			· · · - -
the corner points mentioned in lines 1 and 2 above were, in a field survey on 10-1 & 8-13 1, 9.79, established, mentablished, momented, recommented, recommented, recommented, recommented, recommented, recommented, recommented, recommented, recommented, recommended or records and rules therefore at required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on	the corner points mentioned in lines 1 and 2 above were, in a field survey on 10-1 & 8-13 1, 19.79, established, momented, resonancented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3.4 and 3 above were, in a field survey on 1.5 p. found, recovered, restored, established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: Quarter & sec. cor. set by John Mullett, D.S. in 1845. Bearings were: D-7 Quarter Cor. bet. Sec's. 17-20. Spruce 14, N31°a, 15 lks. Suger 10, South, 20 lks I-11 Sec. Gor. 26-27-34-35. Fir 10, N30°W, 9 lks. & Fir 8, S22°E, 13 lks. 10-Sec.24 South 1/16 corner on west eide of section 24. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Re-established corner midway and on line bet. two sec. cors. I-11 Re-established corner midway and on line bet. two sec. cors. I-12 Re-established corner midway bet. section corner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 12 W. Birch, S76°E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Fine, N58°W, 48.9'. I-11 8" Cedar, N45°L, 5.0' & 6" Cedar, S85°W, 35.9' & 10" Cedar, S43°E, 26.3'. 10-Sec.24 6" Cedar, N44°W, 4.1' & 7" Cedar, Nest, 20.7' & 8" Cedar, S22°W, 4.9' & Corner lies 33' South of rosa. SIGNED BY DATE STATES AGENCIES: DATE STATES AND UNITED STATES AGENCIES: SIGNED BY DATE STATES AGENCIES: DATE STATES AGENCIES S	•	Billy D. Buckler			
Quarter & sec. cor. set by John Mullett, D.S. in 1845. Bearings were: D-7 Quarter Cor. bet. Sec's. 17-20. Spruce 14, N31° 5, 15 lks. « Sugar 10, South, 20 lks I-11 Sec. Cor. 26-27-34-35. Fir 10, N30° W, 9 lks. & Fir 8, S22° E, 13 lks. 10-Sec.24 South 1/16 corner on west side of section 24. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Re-established corner midway and on line bet. two sec. cors. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Placed corner midway bet. section corner to South and ½ corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" place with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76° E, 35.9' & 8" Twin Oak, N3° W, 52.2' & 6" W. Pine, N58° W, 48.9'. I-11 8" Cedar, N35° L, 5.0' & 6" Ceder, S85° W, 35.9' & 10" Cedar, Sk3° E, 26.3'. 10-Sec.24 6" Cedar, N44° W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22° W, 4.9' « Corner lies 33' South of road. DATE3-26-80 BILLY D. Buckler SURVEYOR'S MICHICAN REGISTRATION NO. 8887 DATE SURVEYOR'S MICHICAN REGISTRATION NO. 8887 CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY. CHIEF OF SURVEY PARTY	Quarter & sec. cor. set by John Mullett, D.S. in 1845. Bearings were: D-7 Quarter Cor. bet. Sec's. 17-20. Spruce 14, N31°S, 15 lks. « Sugar 10, South, 20 lks I-11 Sec. Gor. 26-27-34-35. Fir 10, N30°W, 9 lks. & Fir 8, S22°E, 13 lke. 10-Sec.24 South 1/16 corner on west side of section 24. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Re-established corner midway and on line bet. two sec. cors. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Placed corner midway bet. section corner to South and the corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76°E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Pine, N58°W, 48.9'. I-11 8" Cedar, N35°L, 5.0' & 6" Cedar, S85°W, 35.9' & 10" Cedar, S43°E, 26.3'. 10-Sec.24 6" Cedar, N44°W, 4.1' & 7" Cedar, Nest, 20.7' & 8" Cedar, S22°W, 4.9' « Corner lies 33' South of road. SIGNED BY	the re- an Bu an as De	e corner points mentioned in line established, monumented, re-mid rules therefore as required in treau of Land Management or bid 5 above were, in a field survey expressed below and in conform scree of a Court of law:	on and 2 above were, in a conumented, recovered or rethe current manual of survey a decree of a court of law. on	stored as expressed below and by instructions of the United S. Furthermore, that the corner 19, found, recovered, rest Michigan State Board of Registrations.	19 17, established, in conformance with regulations tates Department of the Interior, points mentioned in lines 3, 4 cored, established or re-established
I-11 Sec. Cor. 26-27-34-35. Fir 10, N30°W, 9 1ks. & Fir 8, S22°E, 13 1ks. 10-Sec.24 South 1/16 corner on west side of section 24. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Re-established corner midway and on line bet. two sec. core. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Placed corner midway bet. section corner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76°E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Pine, N58°W, 48.9'. I-11 8" Cedar, N35°E, 5.0' & 6" Cedar, S85°W, 35.9' & 10" Cedar, S43°E, 26.3'. 10-Sec.24 6" Cedar, N44°W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22°W, 4.9' & Corner lies 33' South of road. SIGNED BY BILLY D. Buckler SURVEYOR MICHIGAN REGISTRATION NO. 2887 DATE DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY CHIEF OF SURVEY PARTY DATE	I-11 Sec. Cor. 26-27-34-35. Fir 10, N30°W, 9 lks. & Fir 8, S22°E, 13 lks. 10-Sec.24 South 1/16 cerner on west side of section 24. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Re-established corner midway and on line bet. two sec. cors. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Placed corner midway bet. section corner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1 ⁿ pipe with 4 ⁿ aluminium cap at all corners. New Bearings are: D-7 12 ⁿ W. Birch, S76°E, 35.9' & 8 ⁿ Twin Oak, N3°W, 52.2' & 6 ⁿ W. Pine, N58°W, 48.9'. I-11 8 ⁿ Cedar, N35°L, 5.0' & 6 ⁿ Cedar, S85°W, 35.9' & 10 ⁿ Cedar, S43°E, 26.3'. 10-Sec.24 6 ⁿ Cedar, N44°W, 4.1' & 7 ⁿ Cedar, West, 20.7' & 8 ⁿ Cedar, S22°W, 4.9' & Corner lies 33' South of road. SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY MICHIGAN RESISTRATION BRAILFURGES LANG BURNEY CORN. MICHIGAN RESISTRATION DATE. DATE	Quarter 6	sec. cor. set by John	ent and accessories and/or so Mullett, D.S. in 1	subsequent restoration: .645. Bearings were:	
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: D-7 Re-established corner midway and on line bet. two sec. cors. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Placed corner midway bet. section corner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76 E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Pine, N58 W, 48.9'. I-11 8" Gedar, N35°L, 5.0' & 6" Geder, S85°W, 35.9' & 10" Gedar, S43°E, 26.3'. 10-Sec.24 6" Gedar, N44°W, 4.1' & 7" Gedar, Nest, 20.7' & 8" Gedar, S22°W, 4.9' & Corner lies 33' South of road. SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN RECISTRATION NO. 8887 DATE DATE DATE CHIEF OF BURNEY OF BURNEY PARTY APPROVED AND SIGNED BY DATE DATE	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: D-7 Re-established corner midway and on line bet. two sec. cors. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Placed corner midway bet. section corner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76°E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Pine, N58°W, 48.9'. I-11 8" Cedar, N35°L, 5.0' & 6" Cedar, S85°W, 35.9' & 10" Cedar, S43°E, 26.3'. 10-Sec.24 6" Cedar, N44°W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, 522°W, 4.9' & Corner lies 33' South of road. SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 CHIEF OF SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 CHIEF OF SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY MICHIGAN REGISTRATION DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY MICHIGAN REGISTRATION DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY MICHIGAN REGISTRATION DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY MICHIGAN REGISTRATION DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY MICHIGAN REGISTRATION DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY MICHIGAN REGISTRATION DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY MICHIGAN REGISTRATION DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY	D-7	Quarter Cor. bet. Se	sc's. 17-20. Spruce	, 14, N31 ⁰ ±, 15 1ks. ≅	Sugar 10, South, 20 1ks.
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: D-7 Re-established corner midway and on line bet. two sec. core. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Flaced corner midway bet. section corner to South and the corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76 E, 35.9' & 8" Twin Oak, N3 W, 52.2' & 6" W. Pine, N58 W, 48.9'. I-11 8" Cedar, N35 b, 5.0' & 6" Cedar, S85 W, 35.9' & 10" Cedar, S43 E, 26.3'. 10-Sec.24 6" Cedar, N44 W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22 W, 4.9' & Corner lies 33' South of road. SIGNED BY DATE DATE SIGNED BY DATE CHIEF OF SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY DATE	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: D-7 Re-established corner midway and on line bet. two sec. cors. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Placed corner midway bet. section corner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76 E, 35.9' & 8" Twin Oak, N3 W, 52.2' & 6" W. Pine, N58 W, 48.9'. I-11 8" Cedar, N35°L, 5.0' & 6" Cedar, S85°W, 35.9' & 10" Cedar, S43°E, 26.3'. 10-Sec.24 6" Cedar, N44 W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22°W, 4.9' & Corner lies 33' South of road. SIGNED BY DATE DATE SURVEYORS MICHIGAN REGISTRATION NO. 8887 CHIEF OF SURVEYORS MICHIGAN REGISTRATION NO. 8887 DATE DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY DATE MICHIGAN REGISTRATED LANG BUNVEYOR DATE DATE DATE DATE	I-11	Sec. Cor. 26-27-34-3	35. Fir 10, N30°W,	9 1ks. & Fir 8, S22°E	, 13 lke.
D-7 Re-established corner midway and on line bet. two sec. cors. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Placed corner midway bet. section cerner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76°E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Pine, N58°W, 48.9'. I-11 8" Cedar, N35°E, 5.0' & 6" Cedar, S85°W, 35.9' & 10" Cedar, S43°E, 26.3'. 10-Sec.24 6" Cedar, N44°W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22°W, 4.9' & Corner lies 33' South of road. SIGNED BY DATE SURVEYOR'S MICHIGAN RECISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY DATE DATE APPROVED AND SIGNED BY DATE.	D-7 Re-established corner midway and on line bet. two sec. cors. I-11 Re-established corner by D.P.M. from corners in four directions. 10-Sec.24 Placed corner midway bet. section corner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1 ⁿ pipe with 4 ⁿ aluminium cap at all corners. New Bearings are: D-7 12 ⁿ W. Birch, S76 ^c E, 35.9 ¹ & 8 ⁿ Twin Oak, N3 ^o W, 52.2 ¹ & 6 ⁿ W. Pine, N58 ^o W, 48.9 ¹ . I-11 8 ⁿ Cedar, N35 ^o E, 5.0 ¹ & 6 ⁿ Cedar, S85 ^o W, 35.9 ¹ & 10 ⁿ Cedar, S43 ^o E, 26.3 ¹ . 10-Sec.24 6 ⁿ Cedar, N44 ^o W, 4.1 ¹ & 7 ⁿ Cedar, Nest, 20.7 ¹ & 8 ⁿ Cedar, S22 ^o W, 4.9 ¹ & Corner lies 33 ¹ South of road. SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES ACENCIES: SIGNED BY CHIEF OF SURVEYOR MICHIEVE OF SURVEYOR MICHIEVE OF SURVEYOR DATE DATE DATE DATE DATE DATE DATE	10-Sec.24	South 1/16 corner or	west side of secti	on 24.	
10-Sec.24 Placed corner midway bet. section corner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76 E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Pine, N58 W, 48.9'. I-11 8" Cedar, N35 L, 5.0' & 6" Cedar, S85 W, 35.9' & 10" Cedar, S43 E, 26.3'. 10-Sec.24 6" Cedar, N44 W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22 W, 4.9' & Corner lies 33' South of road. SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY DATE	10-Sec.24 Placed corner midway bet. section corner to South and t corner to North. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76°E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Pine, N58°W, 48.9'. I-11 8" Cedar, N35°E, 5.0' & 6" Cedar, S85°W, 35.9' & 10" Cedar, S43°E, 26.3'. 10-Sec.24 6" Cedar, N44°W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22°W, 4.9' & Corner lies 33' South of road. SIGNED BY DATE3-26-80 BUCKLER SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY MICHIGAN REGISTRATION DATE			- -	~	g comer:
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76 E, 35.9' & 8" Twin Oak, N3 W, 52.2' & 6" W. Pine, N58 W, 48.9'. I-11 8" Cedar, N35 L, 5.0' & 6" Cedar, S85 W, 35.9' & 10" Cedar, S43 E, 26.3'. 10-Sec.24 6" Cedar, N44 W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22 W, 4.9' & Corner lies 33' South of road. SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY DATE	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76°E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Pine, N58°W, 48.9'. I-11 8" Gedar, N35°E, 5.0' & 6" Gedar, S85°W, 35.9' & 10" Gedar, S43°E, 26.3'. 10-Sec.24 6" Gedar, N44°W, 4.1' & 7" Gedar, West, 20.7' & 8" Gedar, S22°W, 4.9' & Corner lies 33' South of road. SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF GURVEY PARTY APPROVED AND SIGNED BY MICHIGAN REGISTRED LAND BUNKEYOR DATE DATE	I-11	Re-established corne	r by D.P.H. from co	rners in four direction	ons.
Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76 E, 35.9' & 8" Twin Oak, N3 W, 52.2' & 6" W. Pine, N58 W, 48.9'. I-11 8" Cedar, N35 L, 5.0' & 6" Cedar, S85 W, 35.9' & 10" Cedar, S43 E, 26.3'. 10-Sec.24 6" Cedar, N44 W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22 W, 4.9' & Corner lies 33' South of road. SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY DATE DATE	Placed 1" pipe with 4" aluminium cap at all corners. New Bearings are: D-7 12" W. Birch, S76°E, 35.9' & 8" Twin Oak, N3°W, 52.2' & 6" W. Pine, N58°W, 48.9'. I-11 8" Cedar, N35°E, 5.0' & 6" Cedar, S85°W, 35.9' & 10" Cedar, S43°E, 26.3'. 10-Sec.24 6" Cedar, N44°W, 4.1' & 7" Cedar, West, 20.7' & 8" Cedar, S22°W, 4.9' & Corner lies 33' South of road. SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY HICHIGAN REGISTRATED LAND BURVEYOR DATE DATE DATE	10-Sec.24	Placed corner midway	bet. section corne	r to South and ‡ corn	er to North.
SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY CHIEF OF SURVEY PARTY DATE DATE 10**Cedar, S43°E, 26.3'. DATE Codar, S43°E, 26.3'. DATE DATE DATE CHIEF OF SURVEY PARTY DATE DATE DATE	Signed by Billy D. Buckler Surveyor's Michigan Registration No. 8887 FOR STATE AND UNITED STATES AGENCIES: Signed by Chief of Survey Party APPROVED AND SIGNED BY MICHIGAN REGISTRED LAND SURVEYOR MICHIGAN REGISTRED LAND SURVEYOR MICHIGAN REGISTRED LAND SURVEYOR MICHIGAN REGISTRED LAND SURVEYOR DATE DATE DATE DATE	C. Placed 1"	pipe with 4" aluminiu	m cap at all corner	s. New Bearings are:	
SIGNED BY Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF GURVEY PARTY APPROVED AND SIGNED BY DATE CHIEF OF GURVEY PARTY DATE CHIEF OF GURVEY PARTY DATE CHIEF OF GURVEY PARTY DATE	SIGNED BY	D-7	12" W. Birch, S76°E,	35.9' & 8" Twin Oal	k, N3 ⁰ W, 52.2' & 6" W.	Pine, N58°W, 48.9'.
SIGNED BY	SIGNED BY	I-11				
Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 2887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY	Billy D. Buckler SURVEYOR'S MICHIGAN REGISTRATION NO. 2687 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY	10 -Sec. 24	6" Cedar, N44°W, 4.1 33' South of road.	' & 7" Cedar, West,	20.7' & 8" Gedar, S22	°W, 4.9' ∝ Corner lies
SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY	SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY	SIC			DATE3_26_80	S BILLY D
SIGNED BY DATE	SIGNED BY	SUI	••			SURVEYOR
CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY	CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR DATE	FO	R STATE AND UNITED STA	TES AGENCIES:		all
APPROVED AND SIGNED BY DATE	MICHIGAN REGISTERED LAND BURVEYOR	SIG		CHIEF OF SURVEY PARTY	DATE	LAND SUI
MICHIGAN REGISTERED LAND BURYEYOR		API	PROVED AND SIGNED BY	MICHIGAN REGIOVERED LAW	DATE	