

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

Four Corners.

| FOR CORNERS OF-- | LOCATED IN-- | CORNER CODE NUMBER |
|--------------------------------------|-------------------|----------------------|
| 1. PUBLIC LAND SURVEY | T. 50 N. R. 6 W. | C-3 B-3 I-10 G-10 |
| 2. PROPERTY CONTROLLING IN SECTION | T. N. S. R. E. W. | |
| 3. MISCELLANEOUS PROPERTY IN SECTION | T. N. S. R. E. W. | |
| 4. LOT NO. | RECORDED PLAT | |
| 5. PRIVATE CLAIMS | | |

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 10-2 & 7-22 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corners placed by Wells Burt, D.S. in 1849.

C-3 Sec. Cor. 5-6-7-8. Bearings were: S. Pine 7", S35°W, 32lks. and B. Oak 7", N35°E, 39 lks
B-3 $\frac{1}{4}$ Cor. Bet. Secs. 6-7. " " Y. Pine 14", S45°W, 37 lks. & Spruce 5", N21°E, 11 lks
I-10 $\frac{1}{4}$ Cor. Bet. Secs. 26-27. " " Pine 16", S19°E, 15 lks. & Pine 6", N19°W, 35 lks.
G-10 $\frac{1}{4}$ Cor. Bet. Secs. 27-28. " " S. Pine 10", S39°W, 37 lks. & S. Pine 10", N31°E, 1.08 cns

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-3 Corner replaced from one original Pine Bearing Tree, a stump 15" high with notch, blaze, and scribe marks in excellent condition. New growth completely covered all marks, with calloused overgrowth showing all the marks in relief.
B-3 Corner replaced from one original Pine Bearing Tree, a log laying on ground, with distinct outline of notch and both faces. Found dead Pine Stub, blazed on four sides, to West of corner location.
I-10 Corner re-established midway and on line bet. two Sec. Cors. Found a 3"x3" wood post, set about 1969, S84°E, 54.2' from this position. Found no evidence of pine stump bottom to agree with this post. Found numerous stumps in vicinity, none could be identified.
G-10 Corner re-placed midway and on line bet. two Sec cors. Found no evidence of originals.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Placed 1" pipe with 4" aluminium cap at all corners.

C-3 New Bearings: 13" W. Pine, N26°W, 27.9' & 6" Twin B. Oak, N75°E, 28.2' & 6" B. Oak, S2°W, 31.6'
B-3 New Bearings: 10" J. Pine, N56°W, 5.4' & 6" J. Pine, S20°W, 26.7' & 8" J. Pine, S88°E, 28.5'
I-10 New Bearings: 13" R. Pine, S43°E, 37.2' & 5" Oak, N16°E, 23.4'
G-10 New Bearings: 8" R. Pine, N20°E, 13.9' & 8" J. Pine, S45°W, 3.3'

SIGNED BY Billy D. Buckler

DATE 10-30-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY

DATE _____

APPROVED AND SIGNED BY _____ MICHIGAN REGISTERED LAND SURVEYOR

DATE _____

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

