

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
CHEBOYGAN
(County)

Located In

Corner Code #

1. Public Land Survey T 38N R 02W B-5
T _____ R _____
2. Property Controlling in Section S T R
S T R
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on January 26, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-5— ¼ Corner common to sections 7 & 18, T38N, R02W

1996 — Remon L.C.R.C. — L.R14, p.297 — Alan J. Granger,
P.S.#52460 — Found 1" pipe with aluminum DNR cap and 4 witnesses from 2006 L.C.R.C.
10" Birch S42°W 36.92' Fd Porter tag
7" Elm N30°W 30.39' Fd Porter tag
9" Aspen N07°E 26.80' Fd Porter tag
4" Balsam S52°E 23.04' Fd Porter tag

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

B-5— ¼ Corner common to sections 7 & 18, T38N, R02W

Found Department of Conservation monument per Remon L.C.R.C. — L.R14, p.297. Monument appeared in good condition. Corner falls 56' North of centerline E-W gravel road. Accepted found DOC monument as a careful and faithful reestablishment of the position of the original corner. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5— ¼ Corner common to sections 7 & 18, T38N, R02W

4" dia. stamped alum. cap on 1" Galvanized pipe

Wit: *N07°E 26.79' to set N&T at old N&T on E side 10" Aspen
*S52°E 23.04' to fd N&T on SW side 3" B. Fir
S36°W 31.96' to set N&T on E side 2",3",4" Triple B. Fir
*S42°W 36.94' to fd N&T on E side 10" dead W. Birch
*N30°W 30.38' to fd N&T on NE side 8" Elm
Set Blue Carsonite Post 1' North

* Witness of previous record.



Carl T Kiiskila

3-9-11

Surveyor's Michigan License No.: 33981