

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

(DICKINSON COUNTY)

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 40 N. R. 30 K. W.	#M-1
2. PROPERTY CONTROLLING IN SECTION 1	T. 40 N. R. 30 K. W.	#2
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on_____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner M-1 (Closing Corner on 4th Correction Line between Section 6, T40N, R29W and Section 1, T40N, R30W):

Wood post (Not found. Found wood stake, by Buckler?)
Cedar 14 S 5E 24 (Not found. Found W. Pine 12 S 6°W 23 lks. by Buckler.)
Cedar 12 S40W 34 (Not found. Found W. Pine 11 S65°E 91 lks. by Buckler.)
(Not found. Found Aspen 12 N 7°E 28 lks. by Buckler.)

Corner 2 (East 1/16 corner on North Side of Section 1, T40N, R30W):
Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner M-1: Corner restored by B. D. Buckler, R.L.S., on 7-20-55, purportedly from "probable" BT's. Re-running of the 4th Corr. Line in 1979 by the undersigned reveals that Buckler's assessment of the BT's is questionable (in this case only) as it is not supported by other measurements to a lake edge and 1/4 post to E and to the section corner W. Therefore, on 8-23-79 I moved Buckler's witnessed corner point S42°47'E 26.26 ft., to a point on the 4th Corr. Line which is proportionately on line bet. a Std. Sec. Cor. 24.372 ch. W and a Std. 1/4 cor. 15.419 ch. E, both restored by Buckler in 1955. Corner 2: Established 9-5-79 on 4th Corr. Line, proportionately on line bet. Std. Sec. Cor. bet. Sec. 32 & 33, 41-29 4.403 ch. W and Std. 1/4 cor. on S side Sec. 33, 41-29 35.388 ch. E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner M-1: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.

*W. Pine 15 N79°W (mag.) 19.0 ft. "S33, NBT"
*W. Pine 16 S77°E (mag.) 36.6 ft. "S 6, NBT"
Red Maple 8 S3°W (mag.) 30.5 ft. "S 1, NBT"
*Same trees used as NBT's by Buckler, re-blazed.
Declination 1° 15' West.

Corner 2: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap, set in rock mound.

Red Maple 12 N31°W (mag.) 12.1 ft. "1/16S, BT"
Red Maple 5 S 2°W (mag.) 7.3 ft. "1/16S, BT"
Declination 2° 15' West.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE March 7, 1984

CHIEF OF SURVEY PARTY
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

