

# SURVEY & REMONUMENTATION

MAR 03 1998

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

1997 DEC 10 PM 3:54

### SECTION

For corners in

Dickinson (County)

Located In:

Corner Code #

Breitung Twp.

1. Public Land Survey

T 40N R 30W M.C. 26  
T R Other # 35  
T R  
T R  
T R

2. Property Controlling in Section

S T R  
S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

REGISTER OF DEEDS  
DICKINSON COUNTY  
RON McBRIDE, CLERK

Register of Deeds Stamp & File Number

I, Robert F. Perkins, in a field survey on Oct. 29, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MEANDER CORNER 26  
35  
Post by James H. Mullett, D.S. 1849  
Original Bearing Trees  
Birch 8" S15°W 06 Lks.  
Birch 6" N40°E 06 Lks.

ACCEPTED BY THE DICKINSON COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT  
345 OF 1990 AT A MEETING HELD ON

12-9-97

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M.C. 26  
35  
No Evidence of Original Corner or Accessories Found.  
It appears that the Lake Level was raised sometime subsequent to the Original Survey, probably by the Construction of the Outlet Control Structure. As a result the Meander Corners were Lost.  
Corner Researched in 1996 Remon. Program.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M.C. 26  
35  
Set 2 1/2" Stamped D.C. Remon. Corner 1031.81 feet Due East from Section Corner 26-27-34 and 35 ± 7' from High Water Line.  
New Witnesses:  
Cedar 10" S63°E (M.B.) 46.00'  
Cedar 4" S55°E (M.B.) 36.10'  
W.Pine 6" S41°W (M.B.) 96.15'  
X on 3' Boulder N77°W (M.B.) -8.70'  
47.5' Northeast of Centerline Steel Tower Line

Signed by Robert F. Perkins

Date Nov. 26, 1997

Surveyor's Michigan License No. 12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN. 1983