Common To THERREN RECORDED LAND CORNER RECORDATION CERTIFICATE 1770 DEC 14 FII 12: 25 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Corner Code # Dickinson Located in: REGISTER OF TITEDS

DICKHISCH GEFFETY

ROM MOTES TO THE CORDS Norway Twp. SURVEY & 1. Public Land Survey M-4 SEMONI MENTATION NOV 1 5 1999 2. Property Controlling in Section 3. Miscellaneous SECTION Property in Sec. Register of Deeds Stamp & File Number \_, Recorded Plat 4. Lot No. 5. Private Claims i, Robert F. Perkins, in a field survey on Nov. 9 , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: M-4 East 2 Corner Section 12 Southeast Corner Section 12 M~5 Post by Wm. A. Burt, D.S. Post by W. A. Burt, D.S. 1846 1846 Original Bearing Trees Original Bearing Trees Cedar 6" S44°E 12 Lk. Cedar 14" N57°W 35 Lk. Fir 6" S80°W 7 Lk. Fir 8" N68°E 15 Lk. ∃. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No Evidence of Original Corner M-4 No Evidence or Original Corner M-5 or its Accessories Remain. or Accessories Found. Found 12" Iron Pipe Found by Billy D. Found 1" Iron Pipe Monument with Buckler, RLS in 1957 and referred to in 4" D.N.R. Cap set by Billy D. Buckler, RLS from G.L.O. BT's in 1957. (01d Report #291) Old Corner Report #290. 1957 Bearing Trees: 1957 Bearing Trees: Tamarack 8" S65°E 36 Lk. (Found)
Tamarack 7" S20°W 54 Lk. (Found) Cedar 24" N71°W 80 Lk. (Found) Cedar 15" S33°W 11 Lk. (Found) \_. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-4 Found and Accepted Pipe Marker **Found and Accepted Corner** described in "B" above. described in "B" above. Set 31" Stamped D.C. Remon Corner inside of Existing Iron Pipe. Witnesses: Cedar 30" N68°W(M.B.) 53.10' Ex. B.T. Cedar 30" S32°W(M.B.) 7.451 Ex. B.T. New Witnesses: Cedar 12" S25°E(M.B.) Spruce 8" N77°W(M.B.) 22.23' Nai1/Tag Spruce 6" N63°E(M.B.) 20.52' Nai1/Tag 25.53' Nail/Tag Fir 6" N71°E(M.B.) 18.48' Nai1/Tag Placed Carsonite Marker T. Division The Tamarack 12" S22°W(M.B.) 35.95' Nail/Tag Tamarack 10" S67°E(M.B.) 24.30' Nail/Tag Placed Carsonite Marker 1.0' South ned by Date Nov. 20, 1998 veyor's Michigan Licante Noed B292E DICKINSON BUINS OF SURVEY PEER GROUP AS THE OFF NOT ACT.

345 OF 1990 AT A MEETING HELD

\_\_

COUNTY REPRESENTATIVE

ROP.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED MAY 14,1975
REVISED OCT., 1985
LIHOR Z. PAGE UND REVISED OCT., 1985