LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	DICK DE ON
1. PUBLIC LAND SURVEY33_	T. 41N N. R. 28W E. W.		(and)
2. PROPERTY CONTROLL- ING IN SECTION——	,T N. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION			
4. LOT NO, RECORDED PLAT			
5. PRIVATE CLAIMS			
			REGISTER OF DEEDS STAMP AND FILING NUMBER

A. Description of original monument and accessories and/or subsequent restoration:

G-II. NE sec. cor. of Section 33.

Billy D. Buckler RLS

Mich. Dept. of Conservation

1" pipe and 4" br. cap

9" black spruce - N75°E - 14 lks.

6" black spruce - N 4°W - 22 lks.

OCT 2 1985

RECEIVED

ENGINEERING-WATER
MANAGEMENT

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- G-11. Found bent over l''pipe on edge of skidder track. Brass cap had been broken off. Both of Buckler's N.B.T.'s were in place but the NE one had been cut, (Part of bottom blaze and notch still on stump.) and the NW one is dead but standing. (Both blazes and scribing plain.) Set NE-W D.N.R. monument in place of bent pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-11. D.N.R. Monument

10" h. maple - \$43°E - 82.6'
6" bl. ash - \$18°E - 48.0'
5" bl. spruce - \$55°W - 20.65'
5" bl. spruce - N72°W - 31.85'
26" w.p. stp. - \$13°E - 18.4'

SIGNED BY Wand B. Baff	ett DATE
SURVEYOR'S MICHICAN DEGLESON ASSESSMENT	21558

(##AL)

9-30-85