

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
 Dickinson

(County)

Located In:

Corner Code =#

1. Public Land Survey	T 42N R 28W	AS
	T R	
	T R	
	T R	
2. Property Controlling in Section	S 18 T 42N R 28W	3
	T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, Stephan J. Szyszkoski, in a field survey on November 09, 1994, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(AS) Corner common to Sections 7-18 T42N-R28W, and Sections 12-13 T42N-R29W. Corner established in 1846 by John and Austin Burt as follows: "80.00 Set post corner of Sections 12&13. Cedar 6 S 41W 10, Hemlock 14 N32W 51, Cedar 10 S19E 35" Found no subsequent record.

(3-Sec. 18) North 1/16 corner between Section 18 T42N-R28W and Section 13 T42N-R29W. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(AS) Original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Found no evidence of subsequent monumentation. Reestablished the corner by proportionate measurement to the original record, on a straight line between Section corner 5282.1' north and Section corner 10564.2' south. At the position for the corner, I placed a 1" I.D.x32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped.

(3-Sec. 18) Found no evidence of prior monumentation at the corner position. Established the corner midway and on a straight line between Section and quarter corners 1320.51' north and south. At the position for the corner, I placed a 1" I.D.x32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. The corner falls in a prairie opening which extends about 200' east, 200' west, 50' north, and 150' south from the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(AS) Set a 1" iron pipe with 4" MDNR cap. Blazed and scribed the following witnesses:

16" Spruce N44W 15.7' "S12 NBT"
 4" Spruce N71E 14.5' "S7 NBT"
 4" Spruce S33E 20.6' "S18 NBT"
 5" Spruce S46W 16.6' "S13 NBT"

Set a 3" squared spruce post adjacent.
 Bearings are magnetic.

(3) Set a 1" iron pipe with 4" MDNR cap. Blazed and scribed the following witnesses:

6" Balsam poplar S59W 38.5' "1/16S BT"
 9" Cherry S42E 33.1' "1/16S BT"
 7" twin Cherry N84E 108.3' "1/16S BT"
 18" Balsam Poplar N18W 30.8' "1/16S BT"

Placed a 4" squared spruce post adjacent. Bearings are magnetic.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5	13	14	15	16	17	18							
6													
7													
8	19	20	21	22	23	24							
9													
10	25	26	27	28	29	30							
11													
12	31	32	33	34	35	36							
13													



Signed by Stephan J. Szyszkoski Date 2-22-95
 Surveyor's Michigan License No. 33986