## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #	
(County) WEST BRANCH TOWNSHIP			
1. Public Land Survey	TR TR		
2. Property Controlling n Section	S 18 T 44N R 27W S 18 T 44N R 27W S T R	09 13	
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No. , Red 5. Private Claims	corded Plat		A B C D E F G H I J K L
	9/19/2013	3AD	2 5 5 4 3 4 2 1 - 1 -
, Jeremy J. Pipp , i	n a field survey on 9/19/201:	3AD do hereby state	, 3
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2			2 4 - 7 - 8 - 9 - 10 - 11 - 12-
above were in conformance with regulations and rules therefore as required in the current manual of survey			y 5
nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of			1 1 1 1 1 1 1 1 1 1 1
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established			
re-established, monumented, recovered, found as expressed below:			
, , , , , , , , , , , , , , , , , , , ,	,		9
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			10 30 29 28 27 26 25
on this certificate.		11	
			12 31 32 33 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (09) Center-East One-Sixteenth corner of Section 18. Not set in original survey, no evidence of subsequent establishment.
- (13) Southeast One-Sixteenth corner of Section 18. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 18.
- (13) Corner position established at the intersection of the South and East One-Sixteenth lines of Section 18. Corner Falls in 1 foot of standing water.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(09)	DNR monument	(13) DNR monument
5" Maple	NO7E 15.75' (1/16S,BT)	5" B. Spruce NO2W 7.52' (1/16S,BT)
8" Maple	S65E 29.55' (1/16S,BT)	6" B. Spruce N38E 22.44' (1/16S,BT)
10" Maple	South 24.97' (1/16S,BT)	11" Cedar N72E 5.10' (1/16S,BT)
4" Maple	N53W 9.76' (1/16S,BT)	9" Cedar S23E 6.23' (1/16S,BT)
All trees are blazed, scribed, and		All trees are blazed, scribed, and
painted. Measurements are to nail in		painted of mets), ements are to nail in
side of tree, bearings are magnetic.		side of tree, coarings are magnetic.

Surveyor's Michigan License No.

October 1, 2013

Rervised Oct., 1995

20289

Signed by

TE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983