LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

OF.	CO1	rna	rc	in

Dickinson	Located In:	Corner Coo	de#				
(County) ELCH TOWNSHIP	_						
. Public Land Survey	TR TR TR						
. Property Controlling Section	S 6 T 44N R	28W 05 28W 16					
. Miscellaneous Property in Sec.	S T R S T R			Register o	of Deeds Star	mp & File N	lumber
. Lot No, Red . Private Claims	corded Plat			ABC	DEF G	7 H I	J K L M
Jeremy J. Pipp , ir	n a field survey on	9/08/2014 9/04/2014	do hereby state	3 6	5 4 -	3	21-
iat under requirements of P.A. sove were in conformance with a structions of the United States I Court of Law and for that the cone rules of the Michigan Board restablished, monumented, recovering the control of the Michigan Board restablished, monumented, recovering the control of the Michigan Board restablished, monumented, recovering the control of the Michigan Board restablished, monumented, recovering the control of the Michigan Board restablished, monumented, recovering the control of the Michigan Board restablished recovering the control of the Michigan Board	regulations and rules therefore Department of the Interior, Bu corner points mentioned in line d of Land Surveyors or by	e as required in the current ureau of Land Management of ss 3, 4 and 5 above were in a Decree of a Court of	manual of survey or by a decree of conformance with Law; established,	6 18	17 16 1	151	13-13-24-13-14-14-13-14-14-15-14-15-14-15-15-15-15-15-15-15-15-15-15-15-15-15-
OTE: Not more than 2 corn n this certificate.	ners, all in the same town a	and range, may be record	ed	9 10 30 2	29 - 28 - 1 12 - 33 - 1	34 3	25-25-36-
. Description of original m	nonument and accessories	and/or subsequent res	,	131			اـــــــــــــــــــــــــــــــــــــ

- 05) Center-North One-Sixteenth corner of Section 6. Not set in original survey, no evidence of absequent establishment.
- 16) East One-Sixteenth corner common to Sections 6 and 7. Not set in original survey, no evidence of subsequent establishment.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 05) Corner position established proportionately and on-line between the Center One-Quarter corner and the North One-Quarter corner of Section 6.
- [16] Corner position established mid-point and on-line between the South One-Quarter corner and the Southeast corner of Section 6.
- 1. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(05) DNR monument	(16) DNR monument				
0" Cedar N68E 28.24' (1/16S,BT)	14" Oak N10E 16.37' (1/16S,BT)				
" B. Spruce S36E 25.05' (1/16S,BT)	12" Spruce N85E 13.03' (1/16S,BT)				
3" Balsam S64W 53.16' (1/16S,BT)	8" Tri. Maple S40W 32.25' (1/16S,BT)				
3" B. Spruce N51W 15.67' (1/16S,BT)	8" Magraf Mic N62W 24.87' (1/16S,BT)				
Ill trees are blazed, scribed, and	All Acces are Cazad, scribed, and				
painted. Measurements are to nail in	pareted. Measurements are to nail in				
side of tree, bearings are magnetic.	side JEFFERRY bearings are magnetic.				
igned by	PROFESSIONALE September 10, 2014				

50447

urveyor's Michigan License No.

For the Michigan Department of Natural Resources

NO.

PER STANDARD STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975