

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>44</u> ^{N.} XX R. <u>29</u> ^{W.} XX	<u>G5</u>
2. PROPERTY CONTROLL- ING IN SECTION <u>9</u>	T. <u>44</u> ^{N.} XX R. <u>29</u> ^{W.} XX	<u>16</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ ^{N.} XX S. _____ R. _____ ^{W.} XX E. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner G5 (Section Corner 9, 10, 15, & 16, T44N, R29W):

Cedar Post (Not found. Found old, squared cedar stump)
Y. Birch N76E 27 (" ") No subsequent accessories found.
Cedar 16 S54W 23 (Possibly found.) No subsequent accessories found.

Corner 16 (East 1/16 corner between Sections 9 & 16, T44N, R29W):

Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner G5: On 9/19/75 placed monument described below at site of an old squared-up cedar stump, from which at the record bearing and distance of S54°W 23 links found the rotted remains of a cedar which could have been the original BT. Corner is N89°59'E 40.162 ch. from an original corner to W (record distance: 40.16 ch.) and N89°50'W 39.863 ch. from an original corner to E (record distance: 39.81 ch.)

Corner 16: Established 10/7/75 on line between 1/4 cor. 20.081 ch. W and Sec. Cor. 20.081 ch. E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner G5: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
White Birch 10 N54°W (mag.) 14.6 ft. "S 9, NBT"
White Spruce 14 N60°E (mag.) 26.2 ft. "S10, NBT"
Sugar Maple 8 S42°E (mag.) 62.0 ft. "S15, NBT"

Corner 16: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap
Sugar Maple 6 N50°W (mag.) 14.5 ft. "1/16S, BT"
Sugar Maple 6 S16°E (mag.) 14.0 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY Carl R. Johnson DATE January 20, 1976

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Arthur O. Enger DATE January 20, 1976

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

