CONS. 4047 4/86

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 43-44 NR 28-29 W

			Dickinson	COUNT
DESCRIPTION OF	CORNER Section con	ner common to Sect	cions 6, 1, 36	and 31.
DESCRIPTION OF C	ORNER MONUMENT_	1" Pipe with 4" F	Brass Cap.	
WITNESSES TO CO	ORNER 9" Tamarack	N 61 E 121	Links, "S 31	WB T "
	_ 9"_Çedar_Stu	b (dead) _ S 17 W_	22 Links, "S 1	NBT"
				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old Cedar Post in place. Found Cedar B.T. bearing N 61 W, 27 Links. Stub standing, dead. All marks very plain.

Corner lies on North edge of floodwater from Beaver Dam.

Corner was placed and witnessed on 17 October 1958.

SURVEYORS SEAL

Silly D. Suckler
SIGNED Billy D. Buckler

DATE _ 4-29-59