LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Gladwin	-		Locate	d In		Comer Code #		
(County)								
1. Public Land Survey		T T	17N	R R	2E.	E8		
Property Controlling in Section	S	Т		R				
3. Miscellaneous	s	_ T		R				
Property in Section	s s	- _T		R			Register of Deeds Stamp & File Number	
4. Lot No:	Recorde	_						
5. Private Claims:							A B C D E F G H I J K L M	
I, <u>Craig W. McVean</u> , in a field survey on <u>Aug. 5</u> , 20 <u>13</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the								
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may								
					9			
be recorded on this certificate.						10 30 29 28 27 26 25		
							12 31 32 33 34 35 36	
A Description of crimina	1	_4			aa aad/a	ar aubanaunat ran		
Description of original monument and accessories and/or subsequent restoration:								
E8 - 1831 - GLO - H. Parke - Set post 1) Pine 34" N7°E 15 L.						 - 2003 – Unrecord Survey – Lapham & Assoc. Job No. G-030304; R. R. Harris (PS #41917) notes corner per 		
2) B. Ash 10" S43°W 23 L. - 1930's – CCC Survey Notes – Random S.					survey recorded L. 2, p. 595. Same distance as Ledy N & S:			
79:54 T Center Estey Road Found ¼ post at 120:35 & 54 W. of random.								
Found stump with Blaze. 160:27 to center E & W road 72 E. of SR center								
- 1993 – Rec. Survey L. 2, p. 596 – D. F. Ledy (PS #21775) – Survey shows calculated position 2665.76' N & S.								
correy shows cale	siatou pos		_000.7	J 14	. O.			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:								
E8 – ¼ Corner common to Sections 20 & 21, T17N, R2E – Set 4" DNR Aluminum Cap on 1" x 4' long galvanized iron pipe from remains of witness #1. Dug at this location but no evidence of wood post was found. Measured Grid bearing and distance of S0°41′25″W 2637.23' (2640′ – GLO) to 'E9' at centerline ± of gravel 'T' intersection. The Civilian Conservation Corps (CCC) Survey had measured south 2634' to center of E-W road. From 'E8' measured North 2694' (2694′ – CCC) to centerline ± of 'T' intersection on Estey Road is noted by CCC survey. No evidence of a monument at the position used by Ledy and Harris. By calculation their								

position would be N20°09'E 30.0' of 'E8'. DNR Monument in swamp as noted by GLO and is accepted as a careful and faithful perpetuation of the position of the original corner.

Date:

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- E8 Stamped 4" DNR Alum. Cap on 1" x 4' long galvanized iron pipe. Set Blue Composite Post 1' East S87°E 8.24' to set N & T in S. side Twin 6" & 11" W. Oak scribed 'XBT' N57°E 32.45' to set N & T in NW side Twin 8" & 13" W. Oak scribed 'XBT' North 50.61' to set N & T in W. side 10" W. Oak scribed 'XBT' S54°W 9.66' to set N & T in NW side 3" W. Oak

Signed by: Surveyor's Michigan License No.:

39088

MICHIG. McVEAN ROFESSION No. 39086

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971 Revised May 14, 1975 Revised Jan. 1983 Revised Oct. 1995