



2020L-00025 STATE OF MICHIGAN **GRAND TRAVERSE COUNTY** RECORDED 12/15/2020 03:15:38 PM **PEGGY HAINES REGISTER OF DEEDS** PAGE 1 OF 2

Land Corner Recordation Certificate

Authority 1970 PA 74, MCL 54 205

Surveyor's Name Craig W McVean					Field Survey Date July 7, 2020								
For corner(s) in	Grand Traverse				County								
Original Public Land Survey Corner					Corner Code								
S	Т		R										
s	т Т		R				ΑВ	CDE	E F (з н і	l J	K L I	M ₁
S	т		R			- 1 ₁				1	;		71
S	Т Т		R			2	6-	5	4	3	2	 1	2
Property Controlling Corner					Corner Code	3	-	- +8	9 🌰	- 10	- 11 -	12	3
S	T		R			- 5				!i	-, •		- 5
S	Т	_	R			ł	40	47	40	4 -	4 4	10	
S	Т		R			- 6	18	- 1,7	1 6	- 15	- 14 -	- 13 -	− 6
S	T		R			⁻ 7 ∤			-	- 		+	∤7
Property Corner					Corner Code	8	· 19	20	21-	- 22	- 23 -	- 24 -	- 8 - 9
S 9	Т	25N	R	12W	9	_10	- 30	- 29	- 28 -	- 27	- 26 -	25	10
S 9	т	25N	R	12W	12	- 10 - 11	;	25	20	: 7	20	25	10 11
s	т .		R										
S	тт		R			-12	- 31	- + - 32	33	- 34	35 -	- 36 -	
Protracted Public Land Survey Corner					Corner Code	-13 ¹	A B	CDE	F (G H I	Ĵ	K L I	վ 13 М
S	T		R			_							
S	Т		R			-							
S	T		R		_	-							
S	Т		R			_							

Part A: Corner History

- 9 CE 1/16 corner Sec 9, T25N, R12W
 - 1920 CSR L 3, p 403 404, L 12, p 274-276 & CPT FB #39, p 157-162 - C P Tuller - Sec 9 Survey Set stake 1) Black Oak 10 in N56°00'W 7 5 feet, 2) B Oak 8" S25°00'W 15' 19 99 1/2 Ch E & W
 - **1980** LCRC L 2, p 422 C F Roser (PS # 12028) Set 1/8 Cor per std BLM instructions Fd Decayed stake from 2 wits, N80°18'W 23 1', per C P Tuller 1920 survey (does not fit proper sec subdivision of section) Drove 5/8" x 3' rerod w/ cedar post and loc tag 3) 4" Maple N35°E 6 2', 4) 13" Twin Oak S52°E 22 0', 5) 12" Oak N82°W 13 9' 1301 90' E & W
- 12 CS 1/16 corner Sec 9, T25N, R12W
 - 1920 CSR L 3, p 403-404, L 12, p 274 276 & CPT FB #39, p 157-162 - C P Tuller - Sec 9 Survey 40 05 - 'F5' to 'F4' Set Post 1) Blk Oak 10" N56°00W 7 5', 2) Blk Oak 8" S29°W 15' [Note same wit's as CE 1/16]
 - 1980 LCRC L 2, p 429 C F Roser (PS # 12028) - Drove 5/8" x 40" rerod w/ RLS Cap and set cedar post w/ loc tag per Standard BLM procedure Centerline Bit Rd due S 106'± 3) 10" Maple N37°W 38 5', 4) 17" Maple S23°E 65 4', 5) 14" Maple S60°W 60 5' 1292 68'- N&S
 - 1993 Rec Survey L 7, p 716 G D Stowe (PS # 25875) - iron found
 - 1996 Rec Survey L 8, p 197 J B Smendzuik (PS # 30895) - Fd Iron
 - 2004 Unrecorded Survey Mitchell & Assoc File No 2004-0799 - R F Mitchell (PS # 28417) iron found

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

- 9 CE 1/16 Corner Sec 9, T25N, R12W Set 2" Alum Cap on 5/8" rebar per standard BLM procedure between accepted remonumentation corners at 'F4' and 'G4' Grid distance E & W is 1313 8'
- Reference Pt 'A' Set spike from the stumps of Tuller's witnesses being N88°45'W 10 97' from corner '9' Dug here but no stake found as it had previously been dug It appears that Tuller had a blunder when establishing this position. His chaining being poorly done in this hilly area. No historic occupation. Tuller position not utilized as corner '9' in this survey.
- Reference Pt 'B' Fd 5/8" rebar per Roser is S69°58'E 12 58' from corner '9' This position is based on a rejected position by Roser at 'F4' and was not utilized as corner '9' in this survey Drove rebar down
- 12 CS 1/16 Corner Sec 9, T25N, R12W Set 2" Alum Cap on 5/8" rebar per standard BLM procedure between accepted remonumentation corners at 'F4' and 'F5' Grid distance N & S is 1309 43'
- -Reference Pt 'C' Found ¾" square iron bar is S41°31′W 8 42′ from Corner '12′ The origin of this bar is unknown. The Tuller notes per the county record are in error. The description noted is the same as the CE 1/16 corner of section 9 where the witnesses were found. No evidence of old Oak witnesses in this area. The notes in the Tuller fieldbook do not indicate a monument or witnesses here but show a random line run east 19.99 ½ Ch. to a post near the SE 1/16 corner. ¾" sq. iron not utilized as corner '12′ in this survey.
- -Reference Pt 'D'- Found 5/8" rebar per Roser and the surveys by Stowe, Smendzuik and Mitchell is N66°36'E 20 99' from Corner '12' This position is based on rejected positions at 'F5' & 'F4' 5/8" rebar is not utilized as corner '12' in this survey

Part C: Field Evidence of Perpetuation or Monumentation of Corner

9 - CE 1/16 Corner Sec 9, T25N, R12W Stamped 2" Aluminum Cap on 5/8" x 36" long iron Rebar Set Blue composite post w/ location tag 1' E N88°45'W 10 97' to spike at Ref Pt 'A' S69°58'E 12 58' to 5/8" rebar at Ref Pt 'B' N38°E 17 14' to set N&T in SE side 12" W Oak N83°E 14 95' to set N&T in N side 7" R Maple S43°W 3 38' to set N&T in SE side 15" Oak 12 – CS 1/16 Corner Sec 9, T25N, R12W Stamped 2" Aluminum Cap on 5/8" x 36" long iron Rebar

Set Blue composite post w/ location tag 1' SE S41°31'W 8 42' to ³/₄" sq iron bar at Ref Pt 'C' N66°36'E 20 99' to 5/8" rebar at Ref Pt 'D' West 14 02 to set N&T in N side 10" Oak N28°W 8 83' to set N&T in E side 7" Oak

Craig W McVean

0400000

Professional Surveyor's License No

4001039088

Prepared By Craig W McVean Michigan Dept of Natural Resources 8015 Mackinaw Trail Cadillac, Michigan 49601



Land Corner Recordation Certificate S 9 T 25N R12W Code 9 S 9 T 25N R12W Code 12 Page 2 of 2

12/14/2020