

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
HOUGHTON
 (County)

Located in:

Corner Code ##

1. Public Land Survey	T	<u>51N</u>	R	<u>36W</u>	<u>CB</u>
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S	<u>19</u>	T	<u>51N</u>	R <u>36W</u>
	S	<u>19</u>	T	<u>51N</u>	R <u>36W</u>
3. Miscellaneous	S		T		R
Property in Sec.	S		T		R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, Stephan J. Szyszkoski, in a field survey on July 07, 1992, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

A. Description of original monument and accessories and/or subsequent restoration:

(CB) Quarter corner between Sections 19 and 20, T51N-R36W. Corner established by U.S. Deputy Surveyor S.W. Higgins, 1848. Found no subsequent record.
 (16) East 1/16 between Sections 19 and 30, T51N-R36W. Corner not established in original survey. Found no subsequent record.
 (7) North 1/16 corner between Section 19 and 20, T51N-R36W. Corner not established in original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(CB) Original post and accessories not recovered. Determined corner to be lost and reestablished the corner by single proportionate measure between recorded corners 2547.24' North and South. Found, but did not accept as the corner, an aluminum pipe with wood post adjacent bearing N41N, 136.8' from the reestablished corner. It appears that the pipe was placed at record bearing and distance from the south. Two blazes face the pipe but do not appear to be more than 15 years old.
 (16) Established corner midway and on a straight line between adjacent recorded corners B9 and C9. Found no monumentation or evidence of use at this position.
 (7) Established corner midway and on a straight line between recorded corners C7 and CB. Found no monumentation or evidence of use at this position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(CB) Placed a 1"x36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet. Blazed and scribed the following new bearing trees: 10" Basswood S39W 5.0' (1/4S NBT) 4" Balsam N05W 28.8' (1/4 NBT) 12" Y. Birch N57E 24.3' (1/4S NBT) 3" Maple S79E 7.9' (1/4S NBT) Placed a 3" squared maple post South 1'	(16) Placed a 1"x36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet. Blazed and scribed the following bearing trees: 6" Hemlock S55E 0.9' (1/16S BT) 8" Maple N66E 9.3' (1/16S BT) 7" Cedar S83W 13.1' (1/16S BT) 7" Maple N45W 7.3' (1/16S BT) Placed a 5" squared cedar post North 1'	(7) Placed a 1"x36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet. Blazed and scribed the following bearing trees: 12" Hemlock N52E 13.1' (1/16S BT) 9" Sugar S60W 14.9' (1/16S BT) 7" Y. Birch N45W 21.0' (1/16S BT) 11" Y. Birch S22E 23.5' (1/16S BT) Placed a 3" squared Maple post North 1'
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Signed by Stephan J. Szyszkoski

Date 7-14-92

Surveyor's Michigan License No. 33986

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, J. 20, 1971
 SURVEYOR No. 33986
 JAN. 1, 1983

