LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

on this certificate.

Houghton (County)	_ Located In:	Corner Code #	
1. Public Land Survey	T 52N R 35W	M6	
2. Property Controlling in Section	S T R S 14 T 52N R 35W S T R	2	
3. Miscellaneous Property in Sec.	S T R S T R		
4. Lot No. 5. Private Claims	corded Plat	20/2040	Register of Deeds Stamp & File Number A B C D E F G H I J K L
I, Stephan J. Szyszkoski , in that under requirements of P.A.		29/2010 27/2010 do hereby state	3
above were in conformance with r instructions of the United States D	regulations and rules therefore as require Department of the Interior, Bureau of La orner points mentioned in lines 3, 4 and	ed in the current manual of survey and Management or by a decree of	5 6 18 17 16 15 14 13 4
the rules of the Michigan Board re-established, monumented, recove	d of Land Surveyors or by a Decree	of a Court of Law; established,	B —19 —20 —23 —22 —23 —24 —9
NOTE: Not more than 2 corne	ers, all in the same town and range		10 30 29 28 27 26 25

A. Description of original monument and accessories and/or subsequent restoration:

(M6) Quarter corner common to Section 13 T52N-R35W and Section 18 T52N-R34W. 1972 - Reestablished by A.O.Enger RLS at intersection of road centerlines as determined by parallel fences on N & S sides of E & W road and E & W sides of N & S road. This position is in line with an old fence going E from the intersection, also. Set 1"ID x36" iron pipe with 4" aluminum cap. NW corner of old garage S57 1/2E 44.9', Nail in power pole S59W 38.2', Fence corner East 33 ft. Monument buried about 6 inches below road surface.

(2-Sec. 14) East 1/16 corner between Sections 11 and 14. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M6) The 1972 monument was not recovered. The monument had been removed by a road grader sometime in the past, according to an adjacent land owner. Reestablished the 1972 position reconstructed as follows: 1) in the intersection of road centerlines; 2) at record bearing and distance from an aluminum nail found in the side of a sawn-off power pole, presumably the 1972 witness object, S59W (now S62W) 38.2' distant; 3) at 33.0' west of an old N-S fence line; 4) in line with the remains of an old fence to the east. The fences on the north and south sides of Peltola road were not found and appear to have been removed. The old garage and the fence corner east (1972 witness objects) were not recovered.

(2-Sec. 14) Established the corner midway and on the Section line between Quarter corner 1333.36' west and Section corner 1333.36' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
7" below the gravel surface in the intersection of
Bear Creek and Peltola Roads.
2.5"O.D.x6.6 ft. Rd. sign post N31W 42.85' to face
Set measuring nail with MDNR tag in the side of:
Power pole JIB41 S62W 36.9'
5" twin Spruce S56E 47.55' mrkd "1/4S NBT"
9" Spruce N58E 44.35' do
Bearings are magnetic.

(2) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 7" Spruce N33E 18.7' mrkd "1/16S BT" 7" Maple N87E 13.95' do 5" Spruce S16W 15.6' do 7" Maple N66W 6.9' do Set sq'd cedar post adjacent. Bearings are magnetic.

AAAAAA				TE OF MICH
Signed by Alephan Sypholist.	Date	10/20/2010		STEPHAN J SZYSZKOSK
Surveyor's Michigan License No. 33986			1	LAND
For the Michigan Department of Natural Resource	es and Environmen	t, Forest Managem	e t Đ	VIS SURVEYOR
40540	69	. 3		No.

16512 16513 FORM APPROVED BY MICHIGAN STATE BOARD

AND 3000 100 y 14, 1975