

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 35W T 52N R 35W T R	G10 G11
2. Property Controlling in Section	S T R S T R S T R	
3. Miscellaneous Property in Sec.	S T R S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 09/20/12 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G10) Quarter corner common to Sections 27 and 28. 1953 - Dean C. DeLaMater RLS reestablished the position for the corner by proportionate measurement while making a partial resurvey of this township. No original evidence was found. Set 1"ID I.pipe with 4" brass cap. 12" Ash N22E 42 links, 10" H.Maple S56W 52 links.

(G11) Corner common to Sections 27-28-33-34. 1953 - Dean C. DeLaMater RLS reestablished the corner position by double proportionate measurement. One possible original B.T. in place, in poor condition. 1997 - The 1953 monument was recovered and recorded by the undersigned (erroneously noted as having been reestablished by Billy D. Buckler RLS). 1997 NBTs: 8" Hemlock S25E 17.9', 7" Y.Birch S43W 2.7', 5" Sugar N42W 9.6', 8" Hemlock N56E 6.9'. Rec. in LC 3, Page 420.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G10) Found the 1953 monument in good condition and at record bearing and distance from the Ash NBT, now 18" DBH with overgrown blazes. The monument is N31°W 13.5' from the midpoint of the mile. However, the 1953 field notes do not explain if the proportionate measurement used to reestablish the corner position was based on adjacent Section corners only, or if it was based, in part, on measurements to feature calls. I accepted the monument as a careful and faithful reestablishment of the position of the original corner.

(G11) Found the 1953 monument in good condition and at record bearing and distance from the 1997 witness trees. Set measuring nails in the side of the 1997 trees and made new measurements to them, as described below. The 1953 NBTs were also found at record bearing and distance, now both stumps but scribing visible on the Hemlock.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G10) Fd. 1"ID Iron pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
18" Ash N27E 28.2' old blazes (1953 NBT)
7" Y.Birch East 13.4' mrkd "1/4S NBT"
8" Maple S61W 13.75' do
10" Maple N40W 7.1' do
Set sq'd Cedar post adjacent.
E=7867188.622 N=233632.639

(G11) Fd. 1"ID Iron pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
10" Hemlock N54E 7.15' old blazes
11" Hemlock S26E 18.2' do
7" Y.Birch S47W 2.9' do
6" Maple N39W 9.85' scribing visible
Set sq'd Cedar post adjacent.
E=7867151.548 N=232821.189

Bearings are magnetic. Coordinates are MCS83 in meters.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 02/27/2013

For the Michigan Department of Natural Resources, Forest Resources Division

