LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Co	orner Code #							
Public Land Survey Property Controlling	T R		L9							
3. Miscellaneous Property in Sec.4. Lot No. Re	S 25 T 52N R S T R S T R S T R		2		Regist	er of Deed	ls Stamp	& File	Numbe	r
5. Private Claims	L9	05/24/20)12	1	A B (D E	F G	H 	I J	K L M
I, Stephan J. Szyszkoski, in that under requirements of P.A. above were in conformance with instructions of the United States a Court of Law and /or that the court of Law and /or the cou	74, Michigan P.A. of 1970, regulations and rules therefor Department of the Interior, I	the corner points re as required in Bureau of Land Ma	mentioned in lines the current manual canagement or by a	1 and 2 ⁴ of survey ⁵ decree of 6	18-	17-	-16	-10	-11-	12-13-
the rules of the Michigan Boar re-established, monumented, recov	d of Land Surveyors or by	a Decree of a	Court of Law; est	tablished, g	19_	_20_	21	_22	23	24
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town	and range, may	be recorded	10 11 12	2-31-	32	-33	-27 -34	35_	36

A. Description of original monument and accessories and/or subsequent restoration:

(L9) Quarter corner common to Sections 24 and 25. 1846 - Established by Deputy Surveyors Higgins and Hubbard midway and on the Section line between Section corners 40.03 chains east and west. Set post. Sugar 10" N44E 16 links, Sugar 12" S10W 11 links. Found no subsequent record.

(2-Sec. 25) East 1/16 corner between Sections 24 and 25. Not previously monumented.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (L9) The true bearing and distance of the line between K9 and M9 was found to be N83 deg. 58'12"E 4900.71 ft. (Rec. as East 5283.96'). Considering the possibility that the 1/4 may have been 'stubbed' out at record bearing and distance from either of the Section corners, a search was conducted at both locations: Due east 40.03 chains east of K9 and Due west 40.03 chains west of M9. No evidence of the position of the original corner was recovered at either of these locations, nor at the single proportionate position for the corner midway and on line between the Section corners. I consider the original corner lost and reestablish it by proportionate measurement to the original record, on the Section line between Section corners 2450.35' easterly and westerly.

(2-Sec. 25) Established the position for the corner midway and on the Section line between Section corner 1225.17' east and Quarter corner 1225.17' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 8" Maple N66W 1.1' mrkd "1/4S NBT" 18" Hemlock S70E 18.9' do 9" Maple S51E 10.75' do 4" Hemlock S12E 25.4' do Set sq'd Cedar post adjacent. Bearings are magnetic.

(2) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 3" Hemlock N68E 17.65' mrkd "1/16S BT" 13" Maple S54E 37.1' do 6" Maple S02E 17.0' do 6" Balsam S63W 3.65' do

Set sq'd cedar post adjacent. Bearings are magnetic.

Date _____07/26/2012

STEPHAN J.
SZYSZKOSKI
LAND
SÜRVEYOR
No.
33986

rse No. 1 33986

For the Michigan Department of Natural Resources, Forest Resources Division

16914

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSION

Revised May 14, 1975 Revised Jan., 1983 Rervised Oct., 1995