

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 36W	G9
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 28 T 52N R 36W	7
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 7 06/10/2008 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G9) Corner common to Sections 21-22-27-28. 1994 - Rewitnessed by C.E.Hein RLS: Found 1.25" iron pipe with old flagged lines to North and West. No evidence of witnesses. Accepted as found. 6" R.Maple N78E 22.17', 6" Birch S50E 3.2', 10" R.Maple S31W 14.59', 7" R.Maple N19W 4.41' (nail with tag 13034 in all)

(7-Sec. 28) North 1/16 corner between 27 and 28. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G9) Recovered the monument of record, as described, in good condition, and at record bearing and distance from the 1994 accessories, all in good condition. The 1994 NBTs Birch S50E and Maple N19W were cut down to facilitate GPS observations. Made new witnesses as described below.

(7-Sec. 28) Established the corner midway and on the Section line between Section corner 1667.89' north and Quarter corner 1667.89' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G9) Found 1.25" ID I.pipe. Fd. nail/tag 13034 in:	(7) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
12" Maple S33W 14.6' overgrown blaze	Set measuring nail with MDNR tag in the side of:
7" Maple N78E 22.25' do	3" Y.Birch N48W 30.15' mrkd "1/16S BT"
Set measuring nail with MDNR tag in the side of:	4" Maple N08E 27.1' do
7" Maple S87W 16.15' mrkd "S28 NBT"	4" Maple N51E 30.05 do
5" Maple S67E 6.35' "S27 NBT"	6" Maple S27E 11.0' do
Bearings are magnetic.	Set sq'd post adjacent. Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/17/2008

For the Michigan Department of Natural Resources, Office of Land and Facilities

