

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 53N R 35W	L13 (GCDB 640100)
2. Property Controlling in Section	S 36 T 53N R 35W	L12 (GCDB 640140)
3. Miscellaneous Property in Sec.	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on L13 10/08/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L13) Standard 1/4 corner on the south side of Section 36. Not a common 1/4 corner to Section 1,
T52N-R35W. 1845 - Established by W.A.Burt, Deputy, midway and on the Township line between Section
corners 40.00 chains east and west. Set post. Hemlock 12" N18°E 47 links, Sugar 12" N15°W 10
links. Notes of P.A. & M.C. Larsen state: "N1/4 Sec. 1 [note - the designation is in error] 1948 -
B.T. Sugar stump NE [sic]". Found no subsequent record.

(L12) Center of Section 36. Found no record of previous monumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L13) The original post and accessories were not recovered. Found no evidence of the position of
the original corner on the ground. Reestablished the position for the corner midway and on the
Township line between Township corner 2659.09' east and Standard Section corner 2659.09' west.

(L12) Established the position for the corner at the intersection of straight lines connecting
opposite 1/4 corners. From the position thus established, found a loosely-set 1-1/4" ID I.pipe
N45°W 15 ft. distant, which was subsequently removed and layed on the ground adjacent to the
established position. The monument leans SE'ly about 0.2' due to subsurface rock. The top center
of the cap marks the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
18" Hemlock S73°E 5.35' mrkd "1/4S NBT"
7" Sugar S68°W 26.5' do
8" Sugar N38°W 14.65' do
4" Sugar N05°E 22.7' do
Set sq'd cedar post adjacent.
E= 7871367.613 N= 240933.574

(L12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
11" Cedar N02°E 23.4' w/loc.tag mrkd "C1/4 BT"
14" Cedar S80°E 18.95' do
12" Y.Birch S30°W 14.55' do
20" Hemlock N52°W 2.0' do
Set sq'd cedar post adjacent.
E= 7871392.094 N= 241733.351

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum
Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/04/2015

For the Michigan Department of Natural Resources, Forest Resources Division

