

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 55N R 32W	C9
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/25/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C9) Section corner common to Sec. 19-20-29-30. Nov. 1997 - A 2 1/4" Brass cap on a 3/4" pipe set by
S.C.Hein PS 32336, approved by the Houghton County Peer Group on Dec. 10, 1997 and recorded in Liber
3 of LCR Page 445, Houghton County Records. Witnesses - a nail and tag #19833 in: 6" Cedar N44E
12.40', 8" Cedar S86E 19.07', 14" Cedar S41E 28.18', 10" Cedar N30W 4.76'. A nail and tag #32336 in:
8" Cedar N19W 24.72'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C9) Found the 1997 monument of record, slightly disturbed by an adjacent windthrown tree. All of
the 1997 witness trees have been disturbed by the wind to a varying degree and are not reliable as
references to reestablish the corner position. Plumbed and reset the 1997 monument at the record
position determined by record bearing and distance from the two adjacent Meander Corners (rec. L.3 of
LCR P 446), also monumented by Mr. Hein and approved by the Peer Group, 78.45' west and 481.18'
south, and forming an angle in the SW quadrant of 88 deg. 43'46". Two of the 1997 witness trees
appear to have stabilized sufficiently to use as new witnesses and are described below. The
remaining 1997 witnesses are not useable.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C9) Set 2 1/4" Brass cap on 3/4" pipe.
Found nail and tag in the side of:
14" Cedar S36E 28.6' tag 19833
8" Cedar N19W 23.7' tag 32336
Set measuring nail with MDNR tag in the side of:
5" Cedar S81E 33.1' mrkd "S29 NBT"
10" Cedar S14W 35.05' "S30 NBT"
Set sq'd cedar post adjacent.
Bearings are magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/17/2011

For the Michigan Department of Natural Resources, Forest Management Division