

Re. Mon. Liber 2, Page 55

1999 REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in PORT AUSTIN Township

Huron
(County)

Located in: Corner Code #

1. Public Land Survey T 19N R 14E 1
T ----- R -----
T ----- R -----
T ----- R -----
2. Property Controlling S T ----- R -----
in Section S T ----- R -----
3. Miscellaneous S T ----- R -----
Property in Sec. S T ----- R -----

STATE OF MICHIGAN
HURON COUNTY
RECORDED

30 DEC 99 2:19 P.M.

FRANCES L. HOLDWICK
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

SECTION

I, Russell L. Brown, in a field survey on Dec. 7, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

Meander Corner
1834 G.L.O. H. Parke D.S. Set Post on border of Lake Huron.
County Surveyors Records - None
County Road Commission Records - None
L.C.R.C. - None
Recorded Plats or Surveys - None
Unrecorded Surveys - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G.L.O. Meander corner position was accessible at this time due to water level being approximately 3 to 4 feet below normal level. However upon return of water level in Lake Huron, to its normal elevation the G.L.O. Meander corner position would be inaccessible. Set 1/2" x 18" Steel Stake capped P.S. 24588 witness to the G.L.O. Meander corner on high bank along shore of Lake Huron.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Witness Corner to Meander Corner
Set 1/2" x 18" Steel Stake capped P.S. 24588
WITNESSES:
S40°W 135.81' to N.E. Corner Concrete Block Foundation of Wood Frame Cottage
N65°W 62.90' to S.E. Corner Concrete Block Foundation of Garage
N15°W 64.65' to Center of Flag Pole
N75°E 4.40' to chiseled "+" top of approximate 36" Dia. Black Stone
East 55.07' to G.L.O. meander corner position
West 1099.93' to H- 13, South 1/4 Corner Section 34, T19N-R14E

Signed by Russell L. Brown
Surveyor's Michigan License No. 24588

Date Dec 27, 1999

Peer group approved at meeting held 12-27-99, RLB

