



97372
RECORDED
HILLSDALE CO. MICH.

REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

'94 NOV 28 AM 11 07

Judy VanZandt
REG. OF DEEDS

For corners in Hillsdale (County) Located In: Corner Code #

- 1. Public Land Survey T 7S R 2W B-1
- 2. Property Controlling in Section S T R
- 3. Miscellaneous Property in Sec. S T R

SURVEY &
REMONUMENTATION

APR 27 1995 Register of Deeds Stamp & File Number

- 4. Lot No. , Recorded Plat
- 5. Private Claims

COMMISSION

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Frederick J. Cutcher, in a field survey on October 27, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
Survey #950, May 6, 1883, George Mark, County Surveyor: Stake; Hickory 4" S. 40 3/4° E., 56 links; Hickory 10" S. 52 1/4° W., 96 links.

Survey #1207, Nov. 3, 1897, George Mark, County Survey: Stone & brick.

R. E. Burris, LCRC Liber 1, Page 385, Jan. 7, 1974: Found P.K. nail used by A. John Hatt and Associates for previous surveys.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found 3/8"x12" iron rod with ribbon on it at road surface. Found 3/4" diameter iron pipe 12" below road surface. Left iron pipe in place and set 3/4"x36" County remonumentation bar in monument box. This position was not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
3/4"x36" County remonumentation bar in monument box
In centerline of E/W road & 11' East of centerline of road to South
West 60.72' from S. 1/4 corner, Sec. 31, T6S, R2W
Found nail in E. side 10" Hickory N. 12° E., 39.0'
Found nail in 4" Cedar S. 32° E., 61.53'
Top center telephone stanchion N. 63° W., 65.34'
Center chain link fence corner N. 66° E., 52.45'
S.W. corner of house (garage) N. 18° E., 106.21'



Signed by Frederick J. Cutcher Date November 23, 1994
Surveyor's Michigan License No. 24592